



FORM
INSP

Rev
X/20

State of Colorado
Oil and Gas Conservation Commission
1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
10/22/2024
Submitted Date:
10/23/2024
Document Number:
714001379

Loc ID
311895

Inspector Name:
Mcdonough, Corey

On-Site Inspection ☐

2A Doc Num: _____

Operator Information:
ECMC Operator Number: 10766
Name of Operator: ARKOMA OPERATIONS LLC
Address: 2121 S COLUMBIA AVE SUITE 101
City: TULSA State: OK Zip: 74114

Status Summary:
☐ THIS IS A FOLLOW UP INSPECTION
☒ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED
Findings:
9 Number of Comments
2 Number of Corrective Actions
☒ Corrective Action Response Requested
ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Price, Andrew	918-260-8324	aprice@arkomaops.com	All SW field inspections
, General		SJBcompliance@arkomaops.com	All SW Inspections
		jpugh@arkomaops.com	Principal Agent

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
89106	WELL	PR	08/15/2007	GW	067-08210	A H TERRELL 1A	RI
282114	WELL	PR	06/19/2018	CBM	067-09094	IGW 106	RI
436554	WELL	PR	01/24/2018	CBM	067-09907	IGW 152	RI

General Comment:

On 10/22/2024 Reclamation Specialist Corey McDonough conducted a Reclamation and Stormwater Inspection at Arkoma Operation's Terrell/IGW Multi Well Location in La Plata County, Colorado.

During the inspection the following compliance issues were observed

- Weeds
- Stormwater

Refer to the "Weeds" and "Stormwater" sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Date Run: 10/23/2024 Doc [#714001379]

Page 1 of 5

Inspected Facilities				
Facility ID: 89106	Type: WELL	API Number: 067-08210	Status: PR	Insp. Status: RI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 282114	Type: WELL	API Number: 067-09094	Status: PR	Insp. Status: RI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 436554	Type: WELL	API Number: 067-09907	Status: PR	Insp. Status: RI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND

Comment: Vegetation is progressing within the interim reclamation areas to 1003 standards – Vegetation is mostly perennial grass/desirable species. Continue to monitor and manage location to comply with 1003 vegetation standards.**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING _____

Comment

Corrective Action

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment

Corrective Action

Date _____

1002c. PROTECTION OF SOILS _____

Comment

Corrective Action

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment

Corrective Action

Date _____

1003a. Waste and Debris removed? _____

Comment No waste/trash observed on location.

Corrective Action

Date _____

Unused or unneeded equipment onsite? _____

Comment No unused equipment observed on location.

Corrective Action

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment

Corrective Action

Date _____

Guy line anchors marked? _____

Comment

Corrective Action

Date _____

1003b. Area no longer in use? Pass Production areas stabilized ? _____
1003c. Compacted areas have been cross ripped? _____
1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
Cuttings management: _____
1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? F

Comment Large patch of Canada Thistle observed in the northwest corner of the disturbance.

Corrective Action Comply with rule 1004.e, treat/remove weeds.

Date 10/30/2024

Overall Interim Reclamation In Process

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: RANGELAND

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____

Well Release on Active Location ☐

Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Rill erosion and failing stormwater BMPs observed in the cutslope portion of the well pad.

Corrective Action:

Comply with rule 1002f. Install or repair required BMPs.

Date: 10/30/2024

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
714001387	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6758240