

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM-66S96W/27SWNE

Location ID: 335459

Date: 10/22/2024



Location Entrance – Photo #04380



Wellheads – Photo #04383

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM-66S96W/27SWNE

Location ID: 335459

Date: 10/22/2024



Separators – Photo #04385



Tank Battery – Photo #04398

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM-66S96W/27SWNE

Location ID: 335459

Date: 10/22/2024



Weathered and Illegible Battery Sign – Photo #04392




No Labeling on Storage Tank – Photo #04397

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM-66S96W/27SWNE

Location ID: 335459

Date: 10/22/2024



Open Wellhead Cellar/No Wildlife Egress – Photo #04381



Stored Supplies – Photo #04390



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM-66S96W/27SWNE

Location ID: 335459

Date: 10/22/2024



Unsecured Separator/Wildlife Entry Hazard – Photo #04386



Open-Ended Line on Separator – Photo #04387

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM-66S96W/27SWNE

Location ID: 335459

Date: 10/22/2024



Open-Ended Line on Separator – Photo #04388



Open-Ended Line on Separator – Photo #04389



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM-66S96W/27SWNE

Location ID: 335459

Date: 10/22/2024



Open-Ended Manifold Line/Stored Supplies – Photo #04396



Open-Ended Load Line – Photo #04394

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM-66S96W/27SWNE

Location ID: 335459

Date: 10/22/2024



Damaged Wellhead Fencing – Photo #04382