

Inspection Photos

Location Name: QB ENERGY PERRYMAN 10-13 (M10SE) Pad

Location #: 334361



Photo # 6810 From entrance to location



Photo # 6811 Location



Inspection Photos

Location Name: QB ENERGY PERRYMAN 10-13 (M10SE) Pad

Location #: 334361



Photo # 6812 Location



Photo # 6813 Location

Inspection Photos

Location Name: QB ENERGY PERRYMAN 10-13 (M10SE) Pad

Location #: 334361



Photo # 6814 Location



Photo # 6815 Location

Inspection Photos

Location Name: QB ENERGY PERRYMAN 10-13 (M10SE) Pad

Location #: 334361



Photo # 6816 Open ended load line



Photo # 6817 Weeds in secondary containment

Inspection Photos

Location Name: QB ENERGY PERRYMAN 10-13 (M10SE) Pad

Location #: 334361



Photo # 6818 Weeds in secondary containment



Photo # 6819 Weeds in secondary containment

Inspection Photos

Location Name: QB ENERGY PERRYMAN 10-13 (M10SE) Pad

Location #: 334361



Photo # 6820 Weeds in secondary containment



Photo # 6821 Weeds in secondary containment