

Construction and Stormwater Inspection

Date: 10/16/2024

Operator: PROVIDENCE OPERATING LLC DBA POCO -
10694

Location ID: 460271

Inspection Document #: 708201701

Weld County, CO



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Double J 35-11 Pad
Location ID: 460271



Photo 1. Facing northeast towards the topsoil stockpile. The topsoil stockpile has evidence of significant weed growth (e.g. russian thistle and kochia). Additionally, it does not appear that all topsoil has been salvaged as the stockpile volume on location does not appear to be reflective of the amount of topsoil throughout the salvageable area.

Inspection Photos
Location Name: Double J 35-11 Pad
Location ID: 460271



Photo 2. Facing north from the southern portion of the stockpile; see comments in Photo 1. Also pictured, example of trash/debris on location (red arrow).

Inspection Photos
Location Name: Double J 35-11 Pad
Location ID: 460271



Photo 3. Facing southeast from the northern portion of the stockpile; see comments in Photo 1.

Inspection Photos
Location Name: Double J 35-11 Pad
Location ID: 460271



Photo 4. Example of trash/debris on location.

Inspection Photos
Location Name: Double J 35-11 Pad
Location ID: 460271



Photo 5. Taken from the southeastern portion of the disturbance area, facing northwest. Disturbance area has evidence of undesirable vegetation (kochia and russian thistle) throughout.

Inspection Photos
Location Name: Double J 35-11 Pad
Location ID: 460271



Photo 6. Southern portion of the location. It appears that some undesirable vegetation has been managed for with evidence of spray indicator (possibly blue dye mixed with herbicide).

Inspection Photos
Location Name: Double J 35-11 Pad
Location ID: 460271



Photo 7. Evidence of Canada thistle (CO List B Noxious Weed) observed on the southern portion of the location. It was unclear if this noxious weed was managed for.

Inspection Photos
Location Name: Double J 35-11 Pad
Location ID: 460271



Photo 8. Evidence of noxious weed (canada thistle) and undesirable vegetation (russian thistle and curly dock) on the western portion of the location.

Inspection Photos
Location Name: Double J 35-11 Pad
Location ID: 460271



Photo 9. Facing southeast from the northwest corner of the location; see comments in Photo 8.

Inspection Photos
Location Name: Double J 35-11 Pad
Location ID: 460271



Photo 10. Stained soils and no observed bull plug at loadout line.

Inspection Photos
Location Name: Double J 35-11 Pad
Location ID: 460271



Photos 11 & 12. Unknown fluid leak at pump/motor next to one of the wellheads.

Inspection Photos
Location Name: Double J 35-11 Pad
Location ID: 460271



Photos 13 & 14. Netting appears to have been shaken out and reinstalled around the secondary containment. The debris that fell off of the netting appears to have mixed with the unknown contents within the secondary containment. All debris/material outside of the secondary containment, and the unknown contents within the secondary containment, must be properly disposed.

Inspection Photos
Location Name: Double J 35-11 Pad
Location ID: 460271



Photo 15. Stained soil observed near the western portion of the tank battery and production facilities.