

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM-66S96W/27SWSE

Location ID: 335398

Date: 10/23/2024



Location – Photo #04427



Location – Photo #04420



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM-66S96W/27SWSE

Location ID: 335398

Date: 10/23/2024



Location – Photo #04425



Location – Photo #04419



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM-66S96W/27SWSE

Location ID: 335398

Date: 10/23/2024



Open Wellhead Cellar/No Wildlife Egress – Photo #04428



Open Wellhead Cellar/No Wildlife Egress – Photo #04429



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM-66S96W/27SWSE

Location ID: 335398

Date: 10/23/2024



**Open-Ended Line on Separator – Photo #04421**



**Insufficient Erosion Control/Degradation – Photo #04430**





## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM-66S96W/27SWSE

Location ID: 335398

Date: 10/23/2024



**Insufficient Erosion Control/Degradation – Photo #04431**



**Insufficient Erosion Control/Degradation – Photo #04432**