

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/23/2024

Submitted Date:

10/24/2024

Document Number:

708302958**FIELD INSPECTION FORM**Loc ID 324239 Inspector Name: Morris, Matthew On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: 1058 COUNTY ROAD 215City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:10 Number of Comments2 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|------------------------------------|---------|
| , TEP | | COGCCInspectionReports@terraep.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 269326 | WELL | PR | 12/22/2003 | OW | 045-09351 | GM 34-27 | PR |

General Comment:**CECMC Inspection Report Summary**

On 10/23/2024 at approximately 12:00, Compliance Inspector Matthew Morris conducted a follow-up inspection at TEP ROCKY MOUNTAIN LLC, GM-66S96W/27SWSE at Location ID #324239 in Garfield County, Colorado.

During the inspection, the following compliance issues were observed:

- 1) Open wellhead cellar; no wildlife egress
- 2) Stormwater; refer to Stormwater section

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

LocationOverall Good: ☐**Signs/Marker:**

| | | | |
|--------------------|--|-------|--|
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | OTHER | | |
| Comment: | Separator units include attached storage tanks. The sight glass on the side of the unit indicates that the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank. | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment: 911/(970)285-9377

Corrective Action:

Date: _____

Good Housekeeping:

| | | | |
|--------------------|---|-------|------------|
| Type | OTHER | | |
| Comment: | Open wellhead cellar with no wildlife egress installed. | | |
| Corrective Action: | Comply with CECMC General Safety rules. | Date: | 10/30/2024 |

Overall Good: ☐**Spills:**

| | | | | |
|------|------|--------|--|--|
| Type | Area | Volume | | |
|------|------|--------|--|--|

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

| | | | |
|--------------------|--------------|-------|--|
| Type | TANK BATTERY | | |
| Comment: | Hog panels | | |
| Corrective Action: | | Date: | |
| Type | SEPARATOR | | |
| Comment: | Hog panels | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | Hog panels | | |
| Corrective Action: | | Date: | |

| | | | |
|-----------------------------------|-----|--|-----------------|
| Equipment: | | | corrective date |
| Type: Bradenhead | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Horizontal Heated Separator | # 4 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Plunger Lift | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Gas Meter Run | # 4 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Bird Protectors | # 4 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|-----------|-----------|---------|--------|
| PRODUCED WATER | 1 | <100 BBLS | STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | 80 bbls | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal | Adequate | Walls Sufficent | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| CONDENSATE | 1 | 300 BBLS | STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | |
| Corrective Action: | | | | | |
| Corrective Action: | | | | | |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

| | | | | | |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Berms | | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| Metal | Adequate | Walls Sufficent | Base Sufficent | Adequate | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |
| Venting: | | | | | |
| Yes/No | NO | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |
| Flaring: | | | | | |
| Type | | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

| Inspected Facilities | | | | | | | | | |
|----------------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 269326 | Type: | WELL | API Number: | 045-09351 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | | | | | | | | | |
| Corrective Action: | | | | Date: | | | | | |

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|--------------------------------|
| | | Ditches | | | | |
| Other | Fail | | | | | Insufficient erosion control |
| Compaction | | | | | | |
| | | Rip Rap | | | | |
| | | Check Dams | | | | |
| | | Sediment Traps | | | | |
| | | | | Material Handling And Spill Prevention | | |
| Berms | | | | | | |
| | | Compaction | | | | |
| | | Gravel | | | | |
| Ditches | | | | | | |
| Gravel | | | | | | |
| Other | Fail | | | | | Transport of sediment off site |
| | | Culverts | | | | |

Comment: Insufficient erosion control; sediment is eroding east of separators and being transported off site and across lease road.

Corrective Action: 1002.f.(2): Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control Stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved pursuant to Rule 1004.

Date: 11/09/2024

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 708302959 | Photo Log | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6759821 |