

**Antler Energy LLC
Federal-Chamberlin 22-1
Location ID: 312863**



Soil staining



Oily waste

Antler Energy LLC
Federal-Chamberlin 22-1
Location ID: 312863



Debris



Well sign missing required information

**Antler Energy LLC
Federal-Chamberlin 22-1
Location ID: 312863**



Staining




Unlabeled tank

Antler Energy LLC
Federal-Chamberlin 22-1
Location ID: 312863



No containment



Oily waste. Stained soil

**Antler Energy LLC
Federal-Chamberlin 22-1
Location ID: 312863**



Open to wildlife



Stained soil

**Antler Energy LLC
Federal-Chamberlin 22-1
Location ID: 312863**



Stained soil




Open end tank valve. Stained soil.

Antler Energy LLC
Federal-Chamberlin 22-1
Location ID: 312863



Open end tank valve. Stained soil.



Unmarked anchors

**Antler Energy LLC
Federal-Chamberlin 22-1
Location ID: 312863**



Location from Northeast corner



Location from Northwest corner

**Antler Energy LLC
Federal-Chamberlin 22-1
Location ID: 312863**



Location from Southwest corner



Location from Southeast corner