

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC CHEVRON-65S97W/16SESW

Location ID: 324330

Date: 10/24/2024



Photo # 7640 Entrance to location




Photo # 7958 Location

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC CHEVRON-65S97W/16SESW

Location ID: 324330

Date: 10/24/2024




Photo # 7942 Location



Photo # 7944 Location

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC CHEVRON-65S97W/16SESW

Location ID: 324330

Date: 10/24/2024



Photo # 7956 Location



Photo # 7981 NW corner of location

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC CHEVRON-65S97W/16SESW

Location ID: 324330

Date: 10/24/2024



Photo # 7982 SW corner of location



Photo # 7983 SE corner of location

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC CHEVRON-65S97W/16SESW

Location ID: 324330

Date: 10/24/2024



Photo # 7950 Wildlife hazard



Photo # 7978 Wildlife hazard

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC CHEVRON-65S97W/16SESW

Location ID: 324330

Date: 10/24/2024



Photo # 7964 Illegible

Photo # 7965 Lacking capacity

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC CHEVRON-65S97W/16SESW

Location ID: 324330

Date: 10/24/2024



Photo # 7966 Lacking capacity

Photo # 7967 Lacking capacity

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC CHEVRON-65S97W/16SESW

Location ID: 324330

Date: 10/24/2024



Photo # 7968 Open ended load line



Photo # 7969 Open ended load line

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC CHEVRON-65S97W/16SESW

Location ID: 324330

Date: 10/24/2024



Photo # 7970 Open ended load line



Photo # 7971 Open ended load line

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC CHEVRON-65S97W/16SESW

Location ID: 324330

Date: 10/24/2024



Photo # 7972 Open ended load line



Photo # 7974 Open ended load lines