

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM/34-4

Location ID: 334896

Date: 10/24/2024



Location Entrance – Photo #04471



Location – Photo #04472

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM/34-4

Location ID: 334896

Date: 10/24/2024



Location – Photo #04478



Location – Photo #04477

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM/34-4

Location ID: 334896

Date: 10/24/2024



Open-Ended Line – Photo #04479



Open-Ended Lines – Photo #04481

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM/34-4

Location ID: 334896

Date: 10/24/2024



Open-Ended Line – Photo #04480



Open-Ended Vent Line – Photo #04483

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM/34-4

Location ID: 334896

Date: 10/24/2024



Insufficient Erosion Control – Photo #04473



Insufficient Erosion Control – Photo #04474

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM/34-4

Location ID: 334896

Date: 10/24/2024



Transport of Sediment Offsite – Photo #04475



Transport of Sediment Offsite – Photo #04476