

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC CHEVRON-65S97W/22NENW

Location ID: 324361

Date: 10/24/2024



Photo # 7099 Entrance to location




Photo # 8015 Location

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC CHEVRON-65S97W/22NENW

Location ID: 324361

Date: 10/24/2024



Photo # 8000 Location



Photo # 8004 Location

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC CHEVRON-65S97W/22NENW

Location ID: 324361

Date: 10/24/2024



Photo # 8013 Location



Photo # 8028 SW corner of location

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC CHEVRON-65S97W/22NENW

Location ID: 324361

Date: 10/24/2024



Photo # 8029 SE corner of location



Photo # 8030 NE corner of location

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC CHEVRON-65S97W/22NENW

Location ID: 324361

Date: 10/24/2024



Photo # 8009 Lacking required information



Photo # 8012 Wildlife hazard



Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC CHEVRON-65S97W/22NENW

Location ID: 324361

Date: 10/24/2024



Photo # 8022 Lacking required information



Photo # 8023 Open ended load line



Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC CHEVRON-65S97W/22NENW

Location ID: 324361

Date: 10/24/2024



Photo # 8025 Open ended load line

