

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC KP 24-23 Pad

Location ID: 324439



Photo # 7153 From entrance to location



Photo # 7154 From entrance to location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC KP 24-23 Pad

Location ID: 324439




Photo # 7155 Location



Photo # 7156 Location



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC KP 24-23 Pad

Location ID: 324439



Photo # 7157 Location



Photo # 7158 Location





## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC KP 24-23 Pad

Location ID: 324439



Photo # 7159 Location



Photo # 7160 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC KP 24-23 Pad

Location ID: 324439



**Photo # 7161 Rupture disc vent line on separator does not comply with CECMC pressure safety device rules**



**Photo # 7162 Rupture disc vent line on separator does not comply with CECMC pressure safety device rules**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC KP 24-23 Pad

Location ID: 324439



**Photo # 7163 PRV vent line does not comply with CECMC pressure safety device rules**



**Photo # 7164 PRV vent line does not comply with CECMC pressure safety device rules**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC KP 24-23 Pad

Location ID: 324439



**Photo # 7165 PRV vent line does not comply with CECMC pressure safety device rules**




**Photo # 7166 PRV vent line does not comply with CECMC pressure safety device rules**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC KP 24-23 Pad

Location ID: 324439



**Photo # 7167 Battery sign does not comply with CECMC rules**

**Photo # 7168 Debris**