

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/21/2024

Submitted Date:

10/21/2024

Document Number:

708302945**FIELD INSPECTION FORM**Loc ID 334656 Inspector Name: Morris, Matthew On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments2 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, CAERUS		ecmc.inspections@qb-energy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
287314	WELL	PR	11/01/2021	GW	045-12962	SHORE 16-10 (PJ16)	PR
287994	WELL	PR	12/01/2021	GW	045-13126	SHORE 16-11BB(PJ16)	PR
287995	WELL	PR	12/01/2021	GW	045-13125	SHORE FEDERAL 16-14 (PJ16)	PR
287996	WELL	PR	11/01/2021	GW	045-13124	SHORE 16-11(PJ16)	PR
288990	WELL	PR	11/01/2021	GW	045-13628	SHORE 16-10BB (PJ16)	PR
289666	WELL	PR	11/01/2021	GW	045-13846	SHORE FEDERAL 16-15BB (PJ16)	PR
289667	WELL	PR	12/01/2021	GW	045-13845	SHORE FEDERAL 16-15 (PJ16)	PR

General Comment:**CECMC Inspection Report Summary**

On 10/21/2024 at approximately 12:05, Compliance Inspector Matthew Morris conducted a follow-up inspection at CAERUS PICEANCE LLC, SHORE-67S95W/16NWSE at Location ID #334656 in Garfield County, Colorado.

During the inspection, the following compliance issues were observed:

- 1) Open-ended line on separator; rupture disk stuck open
- 2) Stormwater; refer to Stormwater section

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

LocationOverall Good: ☐**Signs/Marker:**

Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates that the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/(970)285-2615

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	LOCATION		
Comment:	Barbed wire		
Corrective Action:		Date:	

Equipment:

Type: Bradenhead	# 7		corrective date
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 7		
Comment:			
Corrective Action:		Date:	

Type: Horizontal Heated Separator	# 7	
Comment:	Open-ended line on separator; rupture disk is stuck open. No venting.	
Corrective Action:	Secure equipment to comply with Rule 608.e.	Date: 10/27/2024
Type: Gas Meter Run	# 1	
Comment:		
Corrective Action:		Date:
Type: Plunger Lift	# 7	
Comment:		
Corrective Action:		Date:
Type: Ancillary equipment	# 1	
Comment:	Chemical tank	
Corrective Action:		Date:
Type: Bird Protectors	# 3	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	4	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities				
Facility ID:	287314	Type:	WELL	API Number: 045-12962 Status: PR Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:				Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	287994	Type:	WELL	API Number: 045-13126 Status: PR Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:				Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	287995	Type:	WELL	API Number: 045-13125 Status: PR Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:				Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	287996	Type:	WELL	API Number: 045-13124 Status: PR Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:				Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	288990	Type:	WELL	API Number: 045-13628 Status: PR Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:				Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	289666	Type:	WELL	API Number: 045-13846 Status: PR Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:				Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	289667	Type:	WELL	API Number: 045-13845 Status: PR Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:				Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Fail					Insufficient tracking BMPs
		Ditches				
		Compaction				
		Culverts				
		Gravel				
Compaction	Fail					Lack of stabilization
				Material Handling And Spill Prevention		
Gravel						
Berms						

Comment: Location surface lacks stabilization with insufficient vehicle tracking BMPs in place to minimize transportation of sediment.

Corrective Action: 1002.f.(2): Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control Stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved pursuant to Rule 1004.

Date: 11/06/2024

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403965212	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6755182
708302946	Photo Log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6755180