

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/23/2024

Submitted Date:

10/28/2024

Document Number:

700300761**FIELD INSPECTION FORM**Loc ID 443138 Inspector Name: LABOWSKIE, STEVE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10133Name of Operator: HILCORP ENERGY COMPANYAddress: P O BOX 61229City: HOUSTON State: TX Zip: 77208**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Mcdonough, Corey		corey.mcdonough@state.co.us	
Shorty, Priscilla	505-324-5188	pshorty@hilcorp.com	
Arthur, Denise		denise.arthur@state.co.us	
Burn, Diana		diana.burn@state.co.us	
, General		FarmingtonRegulatoryTechs@hilcorp.com	All SW Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
443139	WELL	SI	06/01/2021	LO	067-09948	ANDERSON 3-5H	TA
443140	WELL	AL	01/29/2019	LO	067-09949	ANDERSON 2-5H	ND

General Comment:

On 10/23/24 SW Compliance supervisor Steve Labowskie was on location to witness MIT of Anderson 3-5H. Well operations were suspended after drilling 9 5/8" surface casing to a depth of 757'. Operator did not have a Form 21 and well was not pre-tested per guidance document. A 15 minute pressure test confirmed casing integrity.

Operator is reporting well as SI (shut in) instead of SO (suspended operations).

Representative did not have a physical Form 21 as required. An exception was made due to the simplicity of wellbore.

Access road was predominately overgrown with weeds, often taller than hood of truck. Weeds present on NW corner of pad and interim revegetation area.

Erosion observed on cut slope with sediment migrating onto pad.

Appears that interim reclamation and corrective actions from 2020 FIR doc#693902555 have not been completed.

Location**Lease Road:**

Type	Other		
comment:	Majority of access overgrown with weeds and tall vegetation, see photos 15 & 16		
Corrective ActionL		Date:	

Overall Good: ☐**Emergency Contact Number:**

Comment:	Well sign at begining of access road. Note: sign for AL status well is also present and is not required.		
Corrective Action:		Date:	

Good Housekeeping:

Type	WEEDS		
Comment:	Kochia present in NW corner of pad, see photo 14		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	443139	Type:	WELL	API Number:	067-09948	Status:	SI	Insp. Status:	TA
Idle Well									
Purpose:		<input type="checkbox"/> Shut In		<input type="checkbox"/> Temporarily Abandoned		Reminder:			
Comment:		<div>Well currently reported as SI instead of SO (suspended operations). SI wells must be readily capable of producing. This well has not been completed, casing shoe/cement not drilled out.</div> <div>9 5/8" surface casing set at 757', casing was full of water and isolated with a "duct cover". Testing head was installed, casing had not been pre-tested per guidance document. Casing was pressured up to 565 psig</div> <div>Intial pressure 565</div> <div>5 min 563</div> <div>10 min 561</div> <div>15 min 560</div>							
Corrective Action:		Report correct well status on nonthly Form 7					Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	443140	Type:	WELL	API Number:	067-09949	Status:	AL	Insp. Status:	ND
Idle Well									
Purpose:		<input type="checkbox"/> Shut In		<input type="checkbox"/> Temporarily Abandoned		Reminder:			
Comment:									
Corrective Action:							Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND, TIMBER

Comment: [Appears CAs from FIR doc#693902555 have not been completed](#)**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING _____

Comment _____

Corrective Action _____ Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____ Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____ Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____ Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____ Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____ Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____ Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____ Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: RANGELAND

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	In Process					

Comment:

Fill erosion and sediment migration onto pad observed, see photos 12 & 13

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

ECMC Comments		
Comment	User	Date
See FIR doc#693902555 and follow up with ECMC Engineering, Reclamation and Financial Assurance staff	labowsks	10/28/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700300765	INSPECTION PHOTOS	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6763131