

Inspection Photos
Location Name: CHAMPLIN 485 AMOCO #1
Location ID: 320071




Photo #1 Location sign.



Photo # 2 Tanks (crude oil).

Inspection Photos
Location Name: CHAMPLIN 485 AMOCO #1
Location ID: 320071



Photo #3 Tanks (crude oil) & weeds with in berm.




Photo #4 Vertical Separators.

Inspection Photos
Location Name: CHAMPLIN 485 AMOCO #1
Location ID: 320071



Photo #5 Debris around separator house.



Photo #6 P/W tank, weeds on berm & NFPA placard faded and needs replaced .

Inspection Photos
Location Name: CHAMPLIN 485 AMOCO #1
Location ID: 320071



Photo #7 Facility pit. Weeds with in pit and large reels in pit.



Photo #8 Facility pit. Weeds with in pit and large reels in pit)

Inspection Photos
Location Name: CHAMPLIN 485 AMOCO #1
Location ID: 320071



Photo #9 Facility pit. Weeds with in pit and large reels in pit.



Photo #10 no BMPs in place to prevent berm sediment from leaving location.

Inspection Photos
Location Name: CHAMPLIN 485 AMOCO #1
Location ID: 320071



Photo #11 Facility pit. Weeds with in pit and large reels in pit.



Photo #12 Facility pit. Weeds with in pit and large reels in pit.

Inspection Photos
Location Name: CHAMPLIN 485 AMOCO #1
Location ID: 320071



Photo #13 Electrical equipment.



Photo #14 Well head, no sign on well head & weeds around well head.