

Denova Sequestration, LLC

Photo Log

Interim Reclamation and Stormwater Controls



Photo 1: Former parking area adjacent to the location

Gravel was removed

The area was drill seeded and stabilized using mulch and a hydraulic tackifier



Photo 2: Southwest corner of the location

Installed rip rap check dams with Filtrexx wattles

The area was drill seeded and stabilized using mulch and a hydraulic tackifier



Photo 3: South side of the location

Installed rip rap check dams with Filtrexx wattles

The area was drill seeded and stabilized using mulch and a hydraulic tackifier



Photo 4: Eastern topsoil stockpile

Drill seeded the topsoil stockpile and stabilized using mulch and a hydraulic tackifier




Photo 5: Access road

Installed diversion ditches with rip rap check dams and staked wattles
Drill seeded and stabilized using mulch and hydraulic tackifier



Photo 6: Access road

Installed staked wattles
Drill seeded and stabilized using mulch and hydraulic tackifier