

Inspection Photos

ID: 478058

Operator: OGRIS OPERATING LLC

Inspection Date: 10/28/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southwest along the main road to the production facility.



Inspection Photos



Photo 2. Facing southwest toward the access road adjacent to the main road. BMP's need to be installed to prevent sediment transport onto the road. A berm or track pad or other BMP is needed at the area of red arrow.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

ID:478058 | Date: 10/28/2024

Inspection Photos



Photo 3. Facing back toward the main public road. There are rock check dams that have already filled in with sediment. A larger sediment catch may be better to prevent sediment transport onto the road. Also, round rock does not lock together and can easily be displaced.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

ID:478058 | Date: 10/28/2024

Inspection Photos



Photo 4. Facing west. It appears stormwater is flowing cross the location contributing to stormwater erosion in previous photos.



Inspection Photos



Photo 5. Facing northwest toward the tank battery.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

ID:478058 | Date: 10/28/2024

Inspection Photos



Photo 6. The netting on the open top tank does not cover the entire open top tank. Previous CA was not completed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

ID:478058 | Date: 10/28/2024

Inspection Photos




Photo 7. There is oily fluids in the secondary containment. Additionally netting must be installed to prevent wildlife entry. Previous CA was not completed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

ID:478058 | Date: 10/28/2024

Inspection Photos




Photo 8. There is oily fluid inside the tank containment area that needs to be cleaned up.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

ID:478058 | Date: 10/28/2024

Inspection Photos



Photo 9. Facing toward the tank battery. There is still oil stained soils where trucks connect to the hoses.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

ID:478058 | Date: 10/28/2024

Inspection Photos



Photo 10. Facing toward the tank battery. There are oil stained soils that need to be cleaned up. Previous CA was not completed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

ID:478058 | Date: 10/28/2024