

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/23/2024

Submitted Date:

10/28/2024

Document Number:

717000107**FIELD INSPECTION FORM**Loc ID 320174 Inspector Name: Finkenbinder, Chane On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 74165Name of Operator: RENEGADE OIL & GAS COMPANY LLCAddress: 6155 S MAIN STREET #225City: AURORA State: CO Zip: 80016**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**10 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Ingvie, Ed	(303) 680-4725	ed@renegadeoilandgas.com	All Inspections
Espinosa, Bill		billespinosa30@yahoo.com	Inspections
Condill, J.B.	(303) 680-4725	jbcrog@aol.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
202904	WELL	SI	06/01/2018	OW	001-08309	(UPRR) VETTER 21-31	SI

General Comment:[Routine inspection](#)

LocationOverall Good: ☒

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	Weeds around pump jack (it appears that weed mitigation was started just needs finished)		
Corrective Action:	Rule 606: Weeds, dead weeds, trash & debris. Within the designated setback (25 feet around any and all equipment), remove trash, debris and weeds per Rule 606. Corrective Action Date 11/ 15/2024 days. See attached photo2, 3 & 4.	Date:	11/15/2024
Type	TRASH		
Comment:	trash around separator		
Corrective Action:	Rule 606: Weeds, dead weeds, trash & debris. Within the designated setback (25 feet around any and all equipment), remove trash, debris and weeds per Rule 606. Corrective Action Date 11/ 15/2024 days. See attached photo2, 3 & 4.	Date:	11/15/2024

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

			corrective date
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	OTHER	STEEL AST		,	

Comment:							
Corrective Action:						Date:	
<u>Paint</u>							
Condition	Adequate						
Other (Content)							
Other (Capacity)		70bbls					
Other (Type)							
<u>Berms</u>							
Type	Capacity		Permeability (Wall)		Permeability (Base)		Maintenance
Earth	Adequate		Walls Sufficent		Base Sufficent		Adequate
Comment:							
Corrective Action:						Date:	
Contents	#	Capacity	Type		Tank ID	SE GPS	
CRUDE OIL	1	300 BBLs	STEEL AST			39.927734,-104.596047	
Comment:							
Corrective Action:						Date:	
<u>Paint</u>							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
<u>Berms</u>							
Type	Capacity		Permeability (Wall)		Permeability (Base)		Maintenance
Earth	Adequate		Walls Sufficent		Base Sufficent		Adequate
Comment:							
Corrective Action:						Date:	
<u>Wells Served By Facilities Above</u>							
API Number		AirsID					
001-08309							
<u>Venting:</u>							
Yes/No	NO						
Comment:							
Corrective Action:						Date:	
<u>Flaring:</u>							
Type							
Comment:							
Corrective Action:						Date:	

Inspected Facilities

Facility ID: 202904

Type: WELL

API Number: 001-08309

Status: SI

Insp. Status: SI

Idle Well

Purpose: ☒ Shut In

☐ Temporarily Abandoned

Reminder:

Comment: SI

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 11/05/2023

Annual Brhd Completed? Yes

Last Brhd Test Results

Initial Surf Csg Pressure: 0

Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: Appeared to be plumbed to the surface

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<div>CECMC Inspection Report Summary</div> <div>On Thursday October 24th, 2024 at approximately 12:45pm. I, Inspector Chane Finkenbinder, conducted an on-site routine inspection.</div> <div>Operator: RENEGADE OIL & GAS</div> <div>Location name: (UPRR) VETTER #21-31</div> <div>API # 05-001-08309</div> <div>Location ID #: 320174</div> <div>County: Adams</div> <div>While there, I observed a shut in well.</div> <div>Rule 606: Weeds, dead weeds, trash & debris. Within the designated setback (25 feet around any and all equipment), remove trash, debris and weeds per Rule 606. Corrective Action Date 11/ 15/2024 days. See attached photo2, 3 & 4.</div> <div>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.</div> <div>This is a summary of inspection report.</div>	finkenbc	10/28/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717000114	INSPECTION PHOTOS	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6763988