

Inspection Photos

ID: 333545

Operator: OGRIS OPERATING LLC

Inspection Date: 10/28/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing east along the access road.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

ID:333545 | Date: 7/22/2024

Inspection Photos



Photo 2. Facing southeast. The location has been recontoured and reclaimed. Soils have been tracked and lightly hydromulched.



Inspection Photos



Photo 3. Facing east at the north side of the location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

ID:333545 | Date: 7/22/2024

Inspection Photos



Photo 4. Facing east at the center of the location. A berm was installed with rock dams.



Inspection Photos



Photo 5. This drainage was stabilized with rock rip/rap for stormwater run-on..



Inspection Photos



Photo 6. Facing toward the east side of the location. This rip/rap outlet appears to have too much rip/rap and may affect drainage as it appears to be slightly higher grad.



Inspection Photos



Photo 7. This electric utility line needs to be removed by coordinating removal with utility company.



Inspection Photos



Photo 8. Facing back west at the reclaimed location..



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

ID:333545 | Date: 7/22/2024