

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/28/2024

Submitted Date:

10/29/2024

Document Number:

713601576**FIELD INSPECTION FORM**Loc ID 333545 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: **Operator Information:**ECMC Operator Number: 10758Name of Operator: OGRIS OPERATING LLCAddress: PO BOX 53467City: MIDLAND State: TX Zip: 79710**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone        | Email             | Comment |
|--------------|--------------|-------------------|---------|
| WARD, GIENA  |              | gward@ogrisop.com |         |
| BACA, DAVE   | 719-859-4066 | dbaca@ogrisop.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name      | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------|-------------|
| 217360      | WELL | PR     | 11/15/1996  | CBM        | 071-06136 | APACHE CANYON 6-10 | RI          |

**General Comment:**

This is a reclamation inspection of the APACHE CANYON #6-10 location.  
See attached photos and additional details within this report.

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started:                      Date Interim Reclamation Completed:                     

Land Use:                     

Comment:                     

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING                     

Comment                     

Corrective Action                      Date                     

1002b. SOIL REMOVAL AND SEGREGATION                     

Comment                     

Corrective Action                      Date                     

1002c. PROTECTION OF SOILS                     

Comment                     

Corrective Action                      Date                     

1002E. SURFACE DISTURBANCE MINIMIZATION                     

Comment                     

Corrective Action                      Date                     

1003a. Waste and Debris removed?                     

Comment                     

Corrective Action                      Date                     

Unused or unneeded equipment onsite?                     

Comment                     

Corrective Action                      Date                     

Pit, cellars, rat holes and other bores closed?                     

Comment                     

Corrective Action                      Date                     

Guy line anchors marked?                     

Comment                     

Corrective Action                      Date

- 1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_
- 1003c. Compacted areas have been cross ripped? \_\_\_\_\_
- 1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_
- Cuttings management: \_\_\_\_\_
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_
- Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

## RESTORATION AND REVEGETATION

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

## 1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

## Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled Pass

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads \_\_\_\_\_ Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed Pass Locations, facilities, roads, recontoured Pass

Compaction alleviation \_\_\_\_\_ Dust and erosion control In

Non cropland: Revegetated 80% In Cropland: perennial forage \_\_\_\_\_

Weeds present In Process Subsidence \_\_\_\_\_

## 1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment: The location has been recontoured and reclaimed. The soils were tracked and hydromulched for temporary stabilization. There is an electric utility that dead ends at this location that must be removed back to where it is currently in use. Operator will need to coordinate removal with the utility company.

Corrective Action: Remove electric utility per 1004 Rules. Date 11/30/2024

|                           |            |                                 |                     |
|---------------------------|------------|---------------------------------|---------------------|
| Overall Final Reclamation | In Process | Well Release on Active Location | Multi-Well Location |
|---------------------------|------------|---------------------------------|---------------------|

Storm Water:

|                  |                 |                         |                       |               |                          |         |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|                  |                 |                         |                       |               |                          |         |

Comment: The soils are tracked perpendicular and have been lightly hydromulched for temporary stabilization. There is silt fence installed at the edge of the northern reclamation area. There are berms and rip/rap for outlet protection. The outlet protection at the east side of the location appears to be overbuilt and slightly higher gradient. Stormwater BMP's will need to be monitored and maintained to prevent erosion.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

|         |             |            |                 |
|---------|-------------|------------|-----------------|
| Permit: | Facility ID | Permit Num | Expiration Date |
|         | 292611      | 2059124    |                 |
|         | 292611      | 2059124    |                 |

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

|              |                   |   |
|--------------|-------------------|---|
| Document Num | Description       | URL   |
| 713601577    | Inspection Photos | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6764837">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6764837</a> |