

**Caerus Piceance – QB Energy**  
**Piceance Creek Unit-62S97W 10NWSE**  
**Location ID: 335947**



**Vent cap missing**



**Vent cap not in place**

**Caerus Piceance – QB Energy**  
**Piceance Creek Unit-62S97W 10NWSE**  
**Location ID: 335947**




**Vehicle tracking**



**Debris? Unused equipment?**



Caerus Piceance – QB Energy  
Piceance Creek Unit-62S97W 10NWSE  
Location ID: 335947



As location signs are replaced additional information is required

Well sign missing required information





**Caerus Piceance – QB Energy**  
**Piceance Creek Unit-62S97W 10NWSE**  
**Location ID: 335947**



**Well pad from Northwest corner**



**Well pad from Southwest corner**



**Caerus Piceance – QB Energy**  
**Piceance Creek Unit-62S97W 10NWSE**  
**Location ID: 335947**



**Production facility from Southwest corner**



**Production facility from Southeast corner**