

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/23/2024

Submitted Date:

10/23/2024

Document Number:

716201080**FIELD INSPECTION FORM**Loc ID 336285 Inspector Name: Carlile, Craig On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**8 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Oxy		ECMCInspections@Oxy.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
246364	WELL	SI	10/01/2020	GW	123-14161	HSR-SPRINCIN 11-24A	TA

**General Comment:**[This is a corrective action Wellhead audit.](#)[Any corrective actions and associated dates from previous audits or inspections that have not been resolved remain in effect.](#)

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

<b>Good Housekeeping:</b>		
Type	WEEDS	
Comment:	Weeds at wellhead	
Corrective Action:	Comply with Rule 606	Date: 10/31/2024

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: \_\_\_\_\_

☐ Multiple Spills and Releases?

<b>Fencing/:</b>		
Type	WELLHEAD	
Comment:	Pipe panels	
Corrective Action:		Date:

<b>Equipment:</b>			corrective date
Type: Plunger Lift	# 0		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment:	Battery location number: 432201				
Corrective Action:				Date:	

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Comment:					
Corrective Action:					Date: <div></div>
<b><u>Venting:</u></b>					
Yes/No	NO				
Comment:					
Corrective Action:					Date: <div></div>
<b><u>Flaring:</u></b>					
Type					
Comment:					
Corrective Action:					Date: <div></div>

Inspected Facilities

Facility ID: 246364

Type: WELL

API Number: 123-14161

Status: SI

Insp. Status: TA

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder:

Comment: Well not connected with flow line.

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 02/23/2024

Annual Brhd Completed? Yes

Last Brhd Test Results

Initial Surf Csg Pressure: 1

Fluid Type: None

End Surf Csg Pressure: --

Comment: Plumbed to surface.

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
This is a corrective action Wellhead audit. Any corrective actions and associated dates from previous audits or inspections that have not been resolved remain in effect.	carlilec	10/23/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403967597	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6757604">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6757604</a>
716201081	Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6757599">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6757599</a>