

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	PHOTO 5: UNUSED EQUIPMENT (TUBING AND RODS ON WEST EDGE OF LOCATION).		
Corrective Action:	REMOVE UNUSED EQUIPMENT PER RULE 606.	Date:	11/17/2024
Type	WEEDS		
Comment:	PHOTO 6: WEEDS NOT MAINTAINED THROUGHOUT LOCATION.		
Corrective Action:	MAINTAIN WEEDS PER RULE 606.	Date:	11/17/2024

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type:			corrective date
Bradenhead	# 0		
Comment:	PHOTO 7: Bradenhead inaccessible or not visible(wellhead tree does not appear to include a Bradenhead in it original install).		
Corrective Action:	Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2). THIS IS THE SECOND NOTICE IMMEDIATE ACTION IS REQUIRED.	Date:	
Pump Jack	# 1		
Comment:	ELECTRIC DRIVE		
Corrective Action:		Date:	
Ancillary equipment	# 1		
Comment:	ELECTRIC SUPPLY FOR PUMPJACK		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	OTHER	STEEL AST		38.326187,-105.126769
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	210 BBL

Other (Type) _____	
--------------------	--

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment: _____				
Corrective Action: _____				Date: _____

Venting:

Yes/No	NO		
Comment: _____			
Corrective Action: _____			Date: _____

Flaring:

Type		
Comment: _____		
Corrective Action: _____		Date: _____

Inspected Facilities

Facility ID: 210076 Type: WELL API Number: 043-40012 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: _____ Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: _____ Fluid Type: _____

End Surf Csg Pressure: _____

Comment: NO BRADENHEAD TEST REPORTS

10/22/2024

Corrective Action: SUBMIT REPORTS

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
THIS IS A FOLLOW UP TO INSP. DOC #695109069, THE CA FOR ACCESS TO BRADEHEAD HAS NOT BEEN ADDRESSED IMMEDIATE ACTION IS REQUIRED. THE CA'S FOR CRUDE OIL TANK HAVE BEEN ADDRESSED. SEE HOUSE KEEPING AND SECTION AND ATTACHED PHOTOS FOR DETAILS ON NEW CA'S.	beardslt	10/17/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403966992	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6757066
716300176	INSP. PHOTOS	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6757039