

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/30/2024

Submitted Date:

10/30/2024

Document Number:

708302990

**FIELD INSPECTION FORM**

Loc ID 334750 Inspector Name: Morris, Matthew On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

8 Number of Comments

1 Number of Corrective Actions

Corrective Action Response Requested

**Operator Information:**

ECMC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, CAERUS		ecmc.inspections@qb-energy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
283783	WELL	PR	05/01/2023	GW	045-12001	ENCANA 21-6BB(PF21)	PR
283785	WELL	PR	05/01/2023	GW	045-12000	ENCANA 21-6 (PF21)	PR
283787	WELL	PR	05/01/2023	GW	045-11999	ENCANA 21-5 (PF21)	PR
283790	WELL	PR	05/01/2023	GW	045-11998	ENCANA 21-3BB(PF21)	PR
288991	WELL	PR	05/01/2023	GW	045-13627	ENCANA FEDERAL 21-2 (PF 21)	PR
288992	WELL	PR	05/01/2023	GW	045-13626	ENCANA FEDERAL 21-7BB (PF21)	PR
288993	WELL	PR	05/01/2023	GW	045-13625	ENCANA FEDERAL 21-7 (PF21)	PR

**General Comment:**

[CECMC Inspection Report Summary](#)

On 10/30/2024 at approximately 11:15, Compliance Inspector Matthew Morris conducted an on-site inspection at CAERUS PICEANCE LLC, ENCANA-67S95W/21SEW in Location ID #334750 in Garfield County, Colorado.

During the inspection, the following compliance issues were observed:

1) Stored equipment on location

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates that the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	911/(970)285-2615		
Corrective Action:		Date:	_____

<b>Good Housekeeping:</b>			
Type	STORAGE OF SUPL		
Comment:	Stored equipment on location.		
Corrective Action:	Remove stored equipment from location.	Date:	11/07/2024

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: \_\_\_\_\_

Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Bradenhead	# 7		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Liquid nitrogen tank		
Corrective Action:		Date:	

Type: Gas Meter Run	# 1		
Comment:	Summit Midstream		
Corrective Action:			Date:
Type: Gas Meter Run	# 7		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 7		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Chemical tank		
Corrective Action:			Date:
Type: Bird Protectors	# 5		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 7		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	1000 GAL	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		

Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	

**Venting:**

Yes/No	NO			
Comment:				
Corrective Action:				Date:

**Flaring:**

Type				
Comment:				
Corrective Action:				Date:

<b>Inspected Facilities</b>			
Facility ID: <u>283783</u>	Type: <u>WELL</u>	API Number: <u>045-12001</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<b>Producing Well</b>			
Comment:			Date:
Corrective Action:			Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12			
Facility ID: <u>283785</u>	Type: <u>WELL</u>	API Number: <u>045-12000</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<b>Producing Well</b>			
Comment:			Date:
Corrective Action:			Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12			
Facility ID: <u>283787</u>	Type: <u>WELL</u>	API Number: <u>045-11999</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<b>Producing Well</b>			
Comment:			Date:
Corrective Action:			Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12			
Facility ID: <u>283790</u>	Type: <u>WELL</u>	API Number: <u>045-11998</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<b>Producing Well</b>			
Comment:			Date:
Corrective Action:			Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12			
Facility ID: <u>288991</u>	Type: <u>WELL</u>	API Number: <u>045-13627</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<b>Producing Well</b>			
Comment:			Date:
Corrective Action:			Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12			
Facility ID: <u>288992</u>	Type: <u>WELL</u>	API Number: <u>045-13626</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<b>Producing Well</b>			
Comment:			Date:
Corrective Action:			Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12			
Facility ID: <u>288993</u>	Type: <u>WELL</u>	API Number: <u>045-13625</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<b>Producing Well</b>			
Comment:			Date:
Corrective Action:			Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12			

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction						
				Material Handling And Spill Prevention		
Gravel						
		Culverts				
		Compaction				
Berms						
		Ditches				
		Gravel				

Comment: Light gravel and compaction on location and lease road; future stormwater events may create tracking issues. Unable to inspect all Stormwater BMPs due to snow cover.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708302991	Photo Log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6767550">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6767550</a>