

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/28/2024

Submitted Date:

10/29/2024

Document Number:

714201813**FIELD INSPECTION FORM**Loc ID 332862 Inspector Name: Santistevan, Brittani On-Site Inspection ☐ 2A Doc Num: ☐**Operator Information:**ECMC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1700 LINCOLN ST STE 4550City: DENVER State: CO Zip: 80203**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:13 Number of Comments3 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Cholas, Nick		nick.cholas@state.co.us	
Tibbs, Dan	970-539-0664	Dtibbs@kpk.com	
,		cogcc@kpk.com	All Inspections
Watzman, Ross	(303) 825-4822	rwatzman@kpk.com	all inspections.
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240882	WELL	SI	07/01/2024	GW	123-08670	MUSICK-MCCLINTOCK 1	SI

General Comment:[This is an audit of MUSICK-MCCLINTOCK #1 scout card and related documents followed by a field inspection.](#)

LocationOverall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:	Adequate (faded)		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	One tank does not display contents/capacity, other tank does not display sign. See attached photos.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	04/19/2024

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Stained soil inside berm. See attached photos.		
Corrective Action:	Comply with Rule 609. Conduct maintenance on equipment, cleanup stained material and review self inspection processes per Rule 1002.f.(2).d.	Date:	04/19/2024
Type	WEEDS		
Comment:	overgrown vegetation on various areas of location. See attached photo.		
Corrective Action:	Comply with Rule 606.	Date:	04/19/2024

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:	wire		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	wire		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	panel		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Vertical Heater Treater	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	BV CONCRETE		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)	UNKNOWN	
Other (Capacity)	UNKNOWN	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	OTHER	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
-----------	----------	--

Other (Content)	UNKNOWN	
Other (Capacity)	UNKNOWN	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	240882	Type:	WELL	API Number:	123-08670	Status:	SI	Insp. Status:	SI

Idle Well

Purpose:

☒ Shut In

☐ Temporarily Abandoned

Reminder:

EQUIPMENT ONSITE

Comment:

SI; valves appear to be in the closed position.

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test:

04/25/2024

Annual Brhd Completed?

Yes

Last Brhd Test Results

Initial Surf Csg Pressure:

20

Fluid Type:

End Surf Csg Pressure:

0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**ECMC Comments**

Comment	User	Date
<p>THIS IS A FOLLOW UP INSPECTION TO PREVIOUS INSPECTION DOC#: 714201264. All previous corrective actions assigned to this location have not been resolved. All previous corrective actions have been re-assigned to this location with their original corrective action date. No new corrective actions were observed at the time of re-inspection. Please review the following additional information below.</p> <p>ECMC Inspection Report Summary WEATHER CONDITIONS: cloudy, dry ground. On Monday, October 28, 2024 at approximately 1230, I, Inspector Brittani Santistevan, conducted an on-site inspection at MUSICK-MCCLINTOCK #1 (KP Kauffman Company Inc), at location ID: 332862 in WELD COUNTY, Colorado. While there, I observed a shut-in facility. During this inspection the following possible compliance issues were observed: 1. It appears to be one tank that does not display contents/capacity. Another tank does not display any signage (contents/capacity/NFPA placard). Install signs to comply with Rule 605.h. (Corrective Action Date: April 19, 2024) See attached photo #3, 11. 2. It appears to be overgrown vegetation on various areas of location. Comply with Rule 606. (Corrective Action Date: April 19, 2024) See attached photo #2-13. 3. It appears to be stained soil inside earthen berm. Comply with Rule 609. Conduct maintenance on equipment, cleanup stained material and review self inspection processes per Rule 1002.f.(2).d. (Corrective Action Date: April 19, 2024) See attached photo #4, 5.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	santistb	10/29/2024

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
714201814	Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6767889