

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/30/2024

Submitted Date:

10/30/2024

Document Number:

714201817

**FIELD INSPECTION FORM**

Loc ID 318633 Inspector Name: Santistevan, Brittani On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1700 LINCOLN ST STE 4550  
City: DENVER State: CO Zip: 80203

**Findings:**

- 8 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
,		cogcc@kpk.com	<a href="#">All Inspections</a>
Tibbs, Dan	970-539-0664	Dtibbs@kpk.com	
Watzman, Ross	(303) 825-4822	rwatzman@kpk.com	<a href="#">all inspections.</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241766	WELL	SI	07/01/2024	OW	123-09555	MUSICK-MCCLINTOCK 2	SI

**General Comment:**

[This is an audit of MUSICK-MCCLINTOCK #2 scout card and related documents followed by a field inspection.](#)

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:			
Corrective Action:		Date:	

**Good Housekeeping:**

Type	WEEDS		
Comment:	Overgrown vegetation on various areas of location. See attached photos.		
Corrective Action:	Comply with Rule 606.	Date:	04/20/2024

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	WELLHEAD		
Comment:	wire, appears to be in disrepair. See attached photos.		
Corrective Action:	Comply with Rule 603.h.	Date:	11/30/2024

**Equipment:**

					corrective date
Type: Bradenhead	# 1				
Comment:					
Corrective Action:		Date:			
Type: Plunger Lift	# 1				
Comment:					
Corrective Action:		Date:			

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 241766 Type: WELL API Number: 123-09555 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: SI; Valves appear to be in the closed position.

Corrective Action:  Date:

**BradenHead**

Date of Last Brhd Test: 05/23/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:  Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
<p><b>THIS IS A FOLLOW UP INSPECTION TO PREVIOUS INSPECTION DOC#: 714200817. PART OF THE PREVIOUS CORRECTIVE ACTION ASSIGNED TO THIS LOCATION HAS BEEN RESOLVED. THE REMAINING PART HAS BEEN REASSIGNED WITH ITS ORIGINAL CORRECTIVE ACTION DATE. ONE NEW CORRECTIVE ACTION HAS BEEN OBSERVED AT THE TIME OF RE-INSPECTION. PLEASE REVIEW MY FINDINGS AND ADDITIONAL INFORMATION BELOW.</b></p> <p>ECMC Inspection Report Summary                      WEATHER CONDITIONS: cloudy, dry ground.                      On Wednesday, October 30, 2024 at approximately 1130, I, Inspector Brittani Santistevan, conducted an on-site inspection at MUSICK-MCCLINTOCK #2 (KP Kauffman Company Inc), at location ID: 318633 in WELD COUNTY, Colorado.                      While there, I observed a shut-in wellhead.                      During this inspection the following possible compliance issues were observed:                      1. It appears there is overgrown vegetation on various areas of location. Comply with Rule 606. (Corrective Action Date: April 20, 2024) See attached photo #3-7.                      2. It appears the wire fencing surrounding the pumpjack is in disrepair. Comply with Rule 603.h. (Corrective Action Date: November 20, 2024) See attached photo #6.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.                      This is a summary of inspection report.</p>	santistb	10/30/2024

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
714201818	Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6767891">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6767891</a>