

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/23/2024

Submitted Date:

10/25/2024

Document Number:

708302962

FIELD INSPECTION FORM

Loc ID: 324157 Inspector Name: Morris, Matthew On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Findings:

- 10 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
259586	WELL	PR	03/21/2001	GW	045-07756	GM 31-34	PR

General Comment:

[CECMC Inspection Report Summary](#)

On 10/23/2024 at approximately 12:10, Compliance Inspector Matthew Morris conducted a follow-up inspection at TEP ROCKY MOUNTAIN LLC, GM-66S96W/34NWNE at Location ID #324157 in Garfield County, Colorado.

During the inspection, the following compliance issues were observed:

- 1) Chemical tank near wellhead is not labeled
- 2) Open-ended load line on produced water tank

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

Location

Overall Good:

Signs/Marker:		
Type	OTHER	
Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates that the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.	
Corrective Action:		Date:
Type	CONTAINERS	
Comment:	Chemical tank near wellhead is not labeled.	
Corrective Action:	Install sign to comply with Rule 605.h.	Date: 11/24/2024
Type	BATTERY	
Comment:		
Corrective Action:		Date:
Type	WELLHEAD	
Comment:		
Corrective Action:		Date:
Type	TANK LABELS/PLACARDS	
Comment:		
Corrective Action:		Date:

Emergency Contact Number:		
Comment:	911/(970)285-9377	
Corrective Action:		Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No _____
 Comment: _____
 Multiple Spills and Releases?

Fencing/:		
Type	WELLHEAD	
Comment:	Hog panels	
Corrective Action:		Date:
Type	SEPARATOR	
Comment:	Hog panels	
Corrective Action:		Date:
Type	TANK BATTERY	
Comment:	Hog panels	
Corrective Action:		Date:

Equipment:			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Chemical tank		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	STEEL AST		
Comment:	Open-ended load line on tank.				
Corrective Action:	Secure equipment to comply with Rule 608.e.				Date: 03/01/2024

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
------	--

Comment:		
Corrective Action:		Date:

--	--	--

Inspected Facilities

Facility ID: 259586 Type: WELL API Number: 045-07756 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention		
Berms						
		Gravel				
Gravel						
		Rip Rap				
		Ditches				
		Compaction				
Compaction						
		Culverts				
		Sediment Traps				
		Check Dams				

Comment: Light gravel and compaction on location and lease road; future stormwater events may create tracking issues.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403971243	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6761743
708302963	Photo Log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6761727