

Storm Water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 169-18 Pad
Location ID: 335604



Location Overview: Location is within High Priority/Density Habitat areas. Location is approximately 7 yards from a creek/drainage that contributes to the Colorado River.

Section/Township/Range: 18 6S94W


Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 169-18 Pad
Location ID: 335604



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.



Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 169-18 Pad
Location ID: 335604



Photo # 8404 Sediment laden stormwater running off lease road into a vegetated area/insufficient BMP's



Photo # 8405 Sediment laden stormwater running off lease road into a vegetated area/insufficient BMP's

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 169-18 Pad
Location ID: 335604



Photo # 8406 Sediment laden stormwater running off lease road into a vegetated area/insufficient BMP's