

## Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC BOSELY-67S96W/23SWNW

Location ID: 334721

Date: 10/30/2024



Photo # 8338 Entrance to location



Photo # 8349 Location

## Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC BOSELY-67S96W/23SWNW

Location ID: 334721

Date: 10/30/2024



Photo # 8341 Location



Photo # 8345 Location

## Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC BOSELY-67S96W/23SWNW

Location ID: 334721

Date: 10/30/2024



Photo # 8347 Location



Photo # 8355 NE corner of location

## Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC BOSELY-67S96W/23SWNW

Location ID: 334721

Date: 10/30/2024



Photo # 8356 SE corner of location



Photo # 8376 NW corner of location

## Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC BOSELY-67S96W/23SWNW

Location ID: 334721

Date: 10/30/2024



**Photo # 8353 Open ended load line**



**Photo # 8366 Tunnel erosion in ditch, is also a wildlife/personal safety hazard**

## Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC BOSELY-67S96W/23SWNW

Location ID: 334721

Date: 10/30/2024



**Photo # 8368 Tunnel erosion in ditch, is also a wildlife/personal safety hazard**



**Photo # 8369 Tunnel erosion in ditch, is also a wildlife/personal safety hazard**