

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/31/2024

Submitted Date:

11/03/2024

Document Number:

693807883**FIELD INSPECTION FORM**Loc ID 322393 Inspector Name: BROWNING, CHUCK On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 51130Name of Operator: LOCIN OIL CORPORATIONAddress: 600 TRAVIS STREET SUITE 5050City: HOUSTON State: TX Zip: 77002**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Lapham, Ken	979-877-4951	klapham@locin.energy	All Inspections
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector
Gross, Jason		jgross@blm.gov	Silt

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210405	WELL	SI	06/01/2020	GW	045-06161	FEDERAL 31-3	SI

General Comment:[ECMC staff performed a routine field inspection on 10/31/2024.](#)[Issues were found requiring corrective action. See inspection text and photos for details.](#)[Any Corrective Actions from previous inspections that have not been addressed are still applicable.](#)

Location

Lease Road:			
Type	Main		
comment:			
Corrective Action		Date:	
Type	Access		
comment:	Location is not accessible due to washout and rutting.		
Corrective Action	Repair and maintain lease road to comply with rule 204.	Date:	12/03/2024

Overall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 970-858-7546

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:	Hogwire & T-post		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Pipe fence		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	100 BBLS	BV PLASTIC		39.414772,-109.034335	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	210405	Type:	WELL	API Number:	045-06161	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____									
Comment: <input type="text" value="Inactive well notice Doc#403291539 received 1/16/2023."/>									
Corrective Action: <input type="text"/> Date: _____									
BradenHead									
Date of Last Brhd Test: <input type="text" value="05/14/2024"/> Annual Brhd Completed? <input type="text" value="Yes"/>									
Last Brhd Test Results Initial Surf Csg Pressure: <input type="text" value="5"/> Fluid Type: <input type="text" value="NONE"/>									
End Surf Csg Pressure: <input type="text" value="0"/>									
Comment: <input type="text"/>									
Corrective Action: <input type="text"/> Date: _____									
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693807884	Inspection photos 10/31/2024	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6771292