

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC Strait/SG 42-22

Location ID: 430567

Date: 10/30/2024



Oct 30, 2024 at 1:36:03 PM
+39.425804,-108.088016 ±4.72m
De Beque



Oct 30, 2024 at 2:00:34 PM
+39.426649,-108.088197 ±4.68m
De Beque

TEP Rocky Mountain LLC

970-285-9377

SG 42-22 PAD

COC 76294

SG 42-22

SG 31-22

SG 331-22

SG 332-22

SG 341-22

SG 342-22

SG 41-22

SG 431-22

SG 432-22

SG 441-22

SG 442-22

SG 532-22

SWNE SEC. 22/T7S/R96W

GARFIELD COUNTY, CO

EMS 911

ACCESS FROM HWY 6 & 24

Photo # 8384 Entrance to location

Photo # Location

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC Strait/SG 42-22

Location ID: 430567

Date: 10/30/2024



Photo # 8385 Location

Photo # 8390 Location

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC Strait/SG 42-22

Location ID: 430567

Date: 10/30/2024



Photo # 8398 Location



Photo # 8428 NW corner of location

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC Strait/SG 42-22

Location ID: 430567

Date: 10/30/2024



Photo # 8429 NE corner of location



Photo # 8393 PRV vent line does not comply with CECMC pressure safety device rules

Inspection Photos
Location: TEP ROCKY MOUNTAIN LLC Strait/SG 42-22
Location ID: 430567
Date: 10/30/2024



Photo # 8394 PRV vent line does not comply with CECMC pressure safety device rules



Photo # 8395 PRV vent line does not comply with CECMC pressure safety device rules

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC Strait/SG 42-22

Location ID: 430567

Date: 10/30/2024



Photo # 8424 Hole in secondary containment/liner needs maintenance



Photo # 8425 Hole in secondary containment/liner needs maintenance

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC Strait/SG 42-22

Location ID: 430567

Date: 10/30/2024



Photo # 8426 Hole in secondary containment/liner needs maintenance



Photo # 8441 Lack of stabilization/compaction on location/insufficient tracking BMP's

Inspection Photos
Location: TEP ROCKY MOUNTAIN LLC Strait/SG 42-22
Location ID: 430567
Date: 10/30/2024



Photo # 8443 Lack of stabilization/compaction on location/insufficient tracking BMP's

Photo # 8449 Sediment trap needs maintenance