

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/24/2024

Submitted Date:

10/28/2024

Document Number:

717000115

FIELD INSPECTION FORM

Loc ID 319739 Inspector Name: Finkenbinder, Chane On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 74165
 Name of Operator: RENEGADE OIL & GAS COMPANY LLC
 Address: 6155 S MAIN STREET #225
 City: AURORA State: CO Zip: 80016

Findings:

- 8 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Condill, J.B.	(303) 680-4725	jbcrog@aol.com	All Inspections
Espinosa, Bill		billespinosa30@yahoo.com	Inspections
Ingvie, Ed	(303) 680-4725	ed@renegadeoilandgas.com	All Inspections

General Comment:

[Routine inspection](#)

Location

Lease Road:

	Type Access		
comment:	No access to well head.		
Corrective Action:	Rule: 204 ACCESS. Location is not accessible during normal business hours. Provide key, combinations, or alternate method of access to comply with rule 204. Corrective Action Date 11/8/2024. See attached photo # 4.	Date:	11/08/2024

Overall Good:

Emergency Contact Number:

Comment: Adequate

Corrective Action: _____ Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment: _____

Multiple Spills and Releases?

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		39.858597,-104.320187
Comment:					
Corrective Action:					Date:

Paint

Condition Adequate

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Insufficient	Inadequate
Comment:	Erosion under tank			
Corrective Action:	Rule: 603.o: Maintained berms around tank(s). Corrective Action Date 11/29/2024. See attached photo # 3.			Date: 11/29/2024

Wells Served By Facilities Above	AirsID
API Number	API Number
001-06614	AirsID

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:		
Type		
Comment:		
Corrective Action:		Date:

ECMC Comments

Comment	User	Date
<p>CECMC Inspection Report Summary On Thursday October 24th 2024 at approximately 11:52am. I, Inspector Chane Finkenbinder, conducted an on-site inspection. Operator: RENEGADE OIL & GAS Location name: FERGUSON #21-9 API # 05-001-06614 Location ID #: 319739 County: Adams While there, I observed a (no access to well head) well. During this inspection the following possible compliance issues were observed: Rule: 204 ACCESS. Location is not accessible during normal business hours. Provide key, combinations, or alternate method of access to comply with rule 204. Corrective Action Date 11/8/2024. See attached photo # 4. Rule: 603.o: Maintained berms around tank(s). Corrective Action Date 11/29/2024. See attached photo # 3. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	finkenbc	10/28/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403973060	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6763997
717000116	Inspection photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6763989