

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403981052

Date Received:

11/04/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed

0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: 501 N DIVISION BLVD

City: PLATTEVILLE State: CO Zip: 80651

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Binschus, Chris

drew_stormo@oxy.com

chris.binschus@state.co.us

ECMCInspections@oxy.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 708201686

Inspection Date: 10/10/2024

FIR Submit Date: 10/14/2024

FIR Status: _____

Inspected Operator Information:

Company Name: KERR MCGEE OIL & GAS ONSHORE LP

Company Number: 47120

Address: P O BOX 173779

City: DENVER

State: CO

Zip: 80217-3779

LOCATION - Location ID: 407867

Location Name: JEFFERS-65N67W

Number: 8NWNE

County: _____

Qtrqtr: NWNE

Sec: 8

Twp: 5N

Range: 67W

Meridian: 6

Latitude: 40.418663

Longitude: -104.912866

FACILITY - API Number: 05-123-

-00

Facility ID: 407867

Facility Name: JEFFERS-65N67W

Number: 8NWNE

Qtrqtr: NWNE

Sec: 8

Twp: 5N

Range: 67W

Meridian: 6

Latitude: 40.418663

Longitude: -104.912866

CORRECTIVE ACTIONS:

1 CA# 199640

Corrective Action: Perform reclamation in accordance with Rule 1004.

Date: _____

Response: CA COMPLETED

Date of Completion: 10/25/2024

Operator
Comment:

Location was innerseed with smooth brome per surface owner request.

ECMC Decision: _____

ECMC
Representative:

2 CA# 199641

Corrective Action: Immediately install or repair required BMPs per Rule 1002.f. in accordance with good engineering practices.

Date: _____

Response: CA COMPLETED

Date of Completion: 10/25/2024

Operator
Comment:

Rills were repaired, soil was returned from bottom of slope, additional topsoil added and compacted, then seeded.

ECMC Decision: _____

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Rills were repaired and soil was returned to slope. Location was cross inner-seeded with smooth brome per surface owner request.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Drew Stormo

Signed: _____

Title: Advisor HSE Environ Ops

Date: 11/4/2024 1:46:14 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403981052	FIR RESOLUTION SUBMITTED
403981069	2023 Work Completion Report
403981072	CA Work Completion Report

Total Attach: 3 Files