

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/05/2024

Submitted Date:

11/05/2024

Document Number:

716201177

FIELD INSPECTION FORM

Loc ID 330281 Inspector Name: Carlile, Craig On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

- 8 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, Oxy		ECMCInspections@Oxy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
250990	WELL	SI	07/01/2022	GW	123-18793	HSR-M J FARMS 14-7	TA

General Comment:

[This is a corrective action Wellhead audit.](#)
[Any corrective actions and associated dates from previous audits or inspections that have not been resolved remain in effect.](#)

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	<input style="width: 100%;" type="text"/>
Corrective Action:	<input style="width: 100%;" type="text"/>
	Date: _____

Good Housekeeping:			
Type	DEBRIS		
Comment:	Weeds at wellhead.		
Corrective Action:	Comply with rule 606	Date:	11/13/2024

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Pipe panel		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 0		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment:	Battery location number: 330278				
Corrective Action:				Date:	

Paint	
Condition	<input style="width: 100%;" type="text"/>
Other (Content)	<input style="width: 100%;" type="text"/>
Other (Capacity)	<input style="width: 100%;" type="text"/>
Other (Type)	<input style="width: 100%;" type="text"/>

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 250990 Type: WELL API Number: 123-18793 Status: SI Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Well not connected with flowline.

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 01/18/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: Plumbed to surface.

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<u>This is a corrective action Wellhead audit. Any corrective actions and associated dates from previous audits or inspections that have not been resolved remain in effect.</u>	carlilec	11/05/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
716201178	Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6773921