

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/05/2024

Submitted Date:

11/05/2024

Document Number:

716201187**FIELD INSPECTION FORM**Loc ID 330288 Inspector Name: Carlile, Craig On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**8 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Oxy		ECMCInspections@Oxy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
251000	WELL	SI	12/01/2020	GW	123-18803	HSR-TUTTLE 6-8	TA

General Comment:[This is a routine Wellhead audit.](#)[Any corrective actions and associated dates from previous audits or inspections that have not been resolved remain in effect.](#)

LocationOverall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:		Date:	

Good Housekeeping:

Type	WEEDS		
Comment:	Weeds at wellhead		
Corrective Action:	Comply with rule 606	Date:	11/13/2024

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Pipe panels.		
Corrective Action:		Date:	

Equipment:

Type: Plunger Lift	# 0		corrective date
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment:	Battery location number: 336616				
Corrective Action:		Date:			

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 251000

Type: WELL

API Number: 123-18803

Status: SI

Insp. Status: TA

Idle Well

Purpose: ☐ Shut In

☒ Temporarily Abandoned

Reminder:

Comment: Well not connected with flow line.

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 01/10/2024

Annual Brhd Completed? Yes

Last Brhd Test Results

Initial Surf Csg Pressure: 0

Fluid Type: None

End Surf Csg Pressure: --

Comment: Plumbed to surface.

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<div>This is a routine Wellhead audit.</div> <div>Any corrective actions and associated dates from previous audits or inspections that have not been resolved remain in effect.</div>	carlilec	11/05/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
716201188	Photo	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6774181