

Inspection Photos

Operator: LOCIN OIL CORPORATION- 51130

Location Name: FULLER USA #18-12

Location ID: 322507 API #: 05-045-06411

Inspection Date: 10/31/2024 Inspection Doc#: 693807894



Location overview looking N



Wellhead with sign

Inspection Photos

Operator: LOCIN OIL CORPORATION- 51130

Location Name: FULLER USA #18-12

Location ID: 322507 API #: 05-045-06411

Inspection Date: 10/31/2024 Inspection Doc#: 693807894



Separator



Blowdown tank

Inspection Photos

Operator: LOCIN OIL CORPORATION- 51130

Location Name: FULLER USA #18-12

Location ID: 322507 API #: 05-045-06411

Inspection Date: 10/31/2024 Inspection Doc#: 693807894



Tank Battery



Dehydrator