

Inspection Photos

Location: QB ENERGY KEINATH FEDERAL-68S96W/18SWNE

Location ID: 334316

Date: 10/31/2024



Oct 31, 2024 at 1:36:21 PM
+39.353164,-108.149392 ±4.74m
De Beque



Oct 31, 2024 at 1:49:03 PM
+39.353058,-108.149155 ±4.74m
De Beque

CAERUS Caerus Piceance LLC
OIL AND GAS LLC
South Piceance
SWNE SEC-18 8S R96W
PAD G18OU 896
TANK # 81586
UNIT # COC66496A

WELL NAME	API#	LAT	LONG
KEINATH FEDERAL 18-8	05077088650000	39.352864	-108.148791

ACCESSED BY - W. ROAD
IN CASE OF EMERGENCY DIAL
970-285-2615 OR 911

Photo # 8517 Entrance to location

Photo # 8535 Location

Inspection Photos

Location: QB ENERGY KEINATH FEDERAL-68S96W/18SWNE

Location ID: 334316

Date: 10/31/2024



Photo # 8519 Location



Photo # 8527 Location

Inspection Photos

Location: QB ENERGY KEINATH FEDERAL-68S96W/18SWNE

Location ID: 334316

Date: 10/31/2024



Photo # 8534 Location



Photo # 8539 SW corner of location

Inspection Photos

Location: QB ENERGY KEINATH FEDERAL-68S96W/18SWNE

Location ID: 334316

Date: 10/31/2024



Oct 31, 2024 at 1:52:10 PM
+39.352871,-108.148603 ±4.73m
De Beque



Oct 31, 2024 at 2:00:37 PM
+39.353331,-108.149379 ±4.74m
De Beque

Photo # 8540 SE corner of location

Photo # 8547 Loose barbed wire fencing/wildlife hazard
NW/NE side of entrance to location

Inspection Photos

Location: QB ENERGY KEINATH FEDERAL-68S96W/18SWNE

Location ID: 334316

Date: 10/31/2024



**Photo # 8549 Loose barbed wire fencing/wildlife hazard
NW/NE side of entrance to location**



**Photo # 8550 Loose barbed wire fencing/wildlife hazard
NW/NE side of entrance to location**

Inspection Photos

Location: QB ENERGY KEINATH FEDERAL-68S96W/18SWNE

Location ID: 334316

Date: 10/31/2024



**Photo # 8561 Loose barbed wire fencing/wildlife hazard
NW/NE side of entrance to location**



**Photo # 8564 Loose barbed wire fencing/wildlife hazard
NW/NE side of entrance to location**

Inspection Photos

Location: QB ENERGY KEINATH FEDERAL-68S96W/18SWNE

Location ID: 334316

Date: 10/31/2024



Photo # 8553 Tunnel erosion around cellar is also a wildlife/personal safety hazard near NE side of entrance to location



Photo # 8557 Tunnel erosion around cellar is also a wildlife/personal safety hazard near NE side of entrance to location