

Inspection Photos

API: 073-06449

Operator: WIEPKING-FULLERTON ENERGY

Inspection Date: 11/5/2024

County: LINCOLN



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing east toward the former access road. There are areas along the road that have not established perennial vegetation.



Inspection Photos



Photo 4. Facing east along the former road toward the location.



Inspection Photos



Photo 3. Facing southeast at the location. The south side of the location consists of undesirable weeds (Kochia) and has not yet established sufficient perennial vegetation cover.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 4. Facing east at the south side of location. The south side of the location consists of undesirable weeds (Kochia) and has not yet established sufficient perennial vegetation cover.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:073-06449 | Date: 11/5/2024

Inspection Photos



Photo 5. Facing north at the location. Perennial vegetation is progressing at the north side of the location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 6. Facing north toward the surrounding undisturbed reference area.

