

**Storm Water Management and Erosion control**  
**Location Name: TEP Rocky Mountain LLC CLOUGH RMV 238-29 Pad**  
**Location #: 335323**



**Location Overview: Location is within High Priority/Density  
Habitat areas & Bald Eagle Roost Site. Location is  
approximately 15 yards from a drainage that contributes to  
the Colorado River.**

**Section/Township/Range: 29 6S94W**

**Storm water Management and Erosion control**  
**Location Name: TEP Rocky Mountain LLC CLOUGH RMV 238-29 Pad**  
**Location #: 335323**



**North West corner of location.**



**North East corner of location.**



**South West corner of location.**



**South East corner of location.**

**Storm water Management and Erosion control**  
**Location Name: TEP Rocky Mountain LLC CLOUGH RMV 238-29 Pad**  
**Location #: 335323**



**Photo # 9252 Failure to maintain chemical BMP – Chemical tank containment approximately 3/4<sup>th</sup> full of fluid/BMP insufficient to contain possible spill**