

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/28/2024

Submitted Date:

10/29/2024

Document Number:

714201815**FIELD INSPECTION FORM**Loc ID 311363 Inspector Name: Santistevan, Brittani On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1700 LINCOLN ST STE 4550City: DENVER State: CO Zip: 80203**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
☒ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
Watzman, Ross	(303) 825-4822	rwatzman@kpk.com	all inspections.
,		cogcc@kpk.com	All Inspections
Tibbs, Dan	970-539-0664	Dtibbs@kpk.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
247274	WELL	SI	07/01/2024	GW	123-15071	MUSICK MCCLINTOCK 7	SI

General Comment:

[This is an audit of MUSICK-MCCLINTOCK #7 scout card and related documents followed by a field inspection.](#)

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	No operator name displayed on sign. See attached photos.		
Corrective Action:	Install sign to comply with Rule 605.	Date:	08/01/2024

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Good Housekeeping:			
Type	WEEDS		
Comment:	overgrown vegetation surrounding pumpjack. See attached photos.		
Corrective Action:	Comply with rule 606.	Date:	08/01/2024
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment south of pumpjack. See attached photos.		
Corrective Action:	Comply with Rule 606.	Date:	08/01/2024

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 247274

Type: WELL

API Number: 123-15071

Status: SI

Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: EQUIPMENT ONSITE

Comment: SI; valves appear to be in the closed position.

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 03/26/2024

Annual Brhd Completed? Yes

Last Brhd Test Results

Initial Surf Csg Pressure: 25

Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**ECMC Comments**

Comment	User	Date
<p>THIS IS A FOLLOW UP INSPECTION TO PREVIOUS INSPECTION DOC#: 714201266. All previous corrective actions assigned to this location have not been resolved. All previous corrective actions have been re-assigned to this location with their original corrective action date. No new corrective actions were observed at the time of re-inspection. Please review the following additional information below.</p> <p>ECMC Inspection Report Summary WEATHER CONDITIONS: cloudy, dry ground. On Monday, October 28, 2024 at approximately 1300, I, Inspector Brittani Santistevan, conducted an on-site inspection at MUSICK-MCCLINTOCK #7 (KP Kauffman Company Inc), at location ID: 311364 in WELD COUNTY, Colorado. While there, I observed a shut-in facility. During this inspection the following possible compliance issues were observed: 1. It appears the operator name is no longer visible on wellhead sign. Install sign to comply with Rule 605. (Corrective Action Date: August 1, 2024) See attached photo #1. 2. It appears to be overgrown vegetation surrounding the pumpjack. Comply with Rule 606. (Corrective Action Date: August 1, 2024) See attached photo #2-6. 3. It appears to be unused/disconnected equipment south of pumpjack. Comply with Rule 606. (Corrective Action Date: August 1, 2024) See attached photo #4.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	santistb	10/29/2024

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403977080	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6767897
714201816	Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6767890