

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 3-20 Pad

Location ID: 323886



Photo # 9083 From entrance to location




Photo # 9084 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 3-20 Pad

Location ID: 323886



Photo # 9085 Location



Photo # 9086 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 3-20 Pad

Location ID: 323886



Photo # 9087 Location




Photo # 9088 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 3-20 Pad

Location ID: 323886



Photo # 9089 Location



Photo # 9090 PRV vent line does not comply with CECMC pressure safety device rules

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 3-20 Pad

Location ID: 323886



**Photo # 9091 PRV vent line does not comply with CECMC
pressure safety device rules**

