

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL WMC 24-17 Pad

Location ID: 480732



Photo # 8804 From entrance to location

Photo # 8805 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL WMC 24-17 Pad

Location ID: 480732



Photo # 8806 Location



Photo # 8807 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL WMC 24-17 Pad

Location ID: 480732



Photo # 8808 Location

Photo # 8809 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL WMC 24-17 Pad

Location ID: 480732



Photo # 8810 Location



Photo # 8811 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL WMC 24-17 Pad

Location ID: 480732



Photo # 8812 Location



Photo # 8813 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL WMC 24-17 Pad

Location ID: 480732



Photo # 8814 Location



Photo # 8815 Tank battery contains three 500 bbl tanks – FORM 2A submitted by operator only lists 2 tanks/operator is not in compliance with CECMC rules

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL WMC 24-17 Pad

Location ID: 480732




Photo # 8816 PRV vent line does not comply with CECMC pressure safety device rules



Photo # 8817 PRV vent line does not comply with CECMC pressure safety device rules

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL WMC 24-17 Pad

Location ID: 480732



Photo # 8818 PRV vent line does not comply with CECMC pressure safety device rules



Photo # 8819 PRV vent line does not comply with CECMC pressure safety device rules

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL WMC 24-17 Pad

Location ID: 480732



Photo # 8820 PRV vent line & rupture disc vent line do not comply with CECMC pressure safety device rules



Photo # 8821 PRV vent line & rupture disc vent line do not comply with CECMC pressure safety device rules

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL WMC 24-17 Pad

Location ID: 480732



Photo # 8822 PRV vent line does not comply with CECMC pressure safety device rules



Photo # 8823 PRV vent line does not comply with CECMC pressure safety device rules