

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/04/2024

Submitted Date:

11/04/2024

Document Number:

708904967

**FIELD INSPECTION FORM**Loc ID 322314 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 10550

Name of Operator: MUSTANG RESOURCES LLC

Address: P O BOX 13550

City: BAKERSFIELD State: CA Zip: 93389

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

15 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Toews, Wesley		wtoews@blm.gov	
, Mustang		nwelch@vaqueroenergy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210256	WELL	PR	07/01/2024	GW	045-06012	RULISON FEDERAL 35-94-6S-94W	PR

**General Comment:****CECMC Inspection Report Summary**

On 11/04/2024 at approximately 11:41 hours, I, Compliance Specialist, Wayne Smelser

Conducted a follow up inspection at MUSTANG RESOURCES LLC RULISON FEDERAL 35-94-6S-94W Pad.

Location # 322314 in Garfield County Colorado.

Please refer to inspection 708903514 conducted on 04/11/2024, previous corrective action has not been completed.

Location is within High Priority/Density/Black Bear Habitat areas &amp; in close proximity to NSO Habitat area.

Location is approximately 272 yards from Porcupine Creek.

While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Housekeeping - Unused equipment on location with a CA date of 05/11/2024

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This is a summary of inspection report.

Location				
<b>Lease Road:</b>				
Type	Access			
comment:				
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Type	BATTERY			
Comment:	No tank battery			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	911/1-888-291-8588			
Corrective Action:				Date: _____
<b>Good Housekeeping:</b>				
Type	DEBRIS			
Comment:	Debris - please refer to photo log			
Corrective Action:				Date:
Type	UNUSED EQUIPMENT			
Comment:	<p>Unused equipment on location - extra meter house on location &amp; equipment is not in use.</p> <p>Please refer to FORM 4 document # 403769842</p> <p>Operator stated "A meter house has been staged on location for installation of telemetry equipment. Mustang will complete the installation no later than October 31,2024 as instrumentation and electrical team is available."</p> <p>At the time of this inspection meter house has not been hooked up/is unused equipment</p>			
Corrective Action:	The storage or placement of equipment and supplies not necessary for use on location is prohibited.			Date: 05/11/2024
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Equipment:</b>				
Type: Plunger Lift	# 0			corrective date
Comment:	Well is not on plunger lift			
Corrective Action:				Date:
Type: Bradenhead	# 1			

Comment:	No form of pressure monitoring equipment located on bradenhead, bradenhead valve is accessible.			
Corrective Action:			Date:	
Type: Gas Meter Run	# 2			
Comment:	1 meter house is not hooked up & is not in use/unused equipment, please refer to Housekeeping for CA			
Corrective Action:			Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

--	--	--	--

Inspected Facilities									
Facility ID:	210256	Type:	WELL	API Number:	045-06012	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well is not on plunger lift								
Corrective Action:				Date:					

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction				
Other						Rill erosion starting to develop near meter house
		Gravel				Sparse
		Culverts				
Gravel						Sparse to none in most areas
		Ditches				
Compaction						Light compaction in some areas

Comment: Rill erosion starting to develop near meter house

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Please refer to Housekeeping for corrective action	smelserw	11/04/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403981881	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6773120">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6773120</a>
708904968	Inspection 708904967 Stormwater photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6773111">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6773111</a>
708904969	Inspection 708904967 photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6773113">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6773113</a>