

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/12/2024

Submitted Date:

11/14/2024

Document Number:

708700063**FIELD INSPECTION FORM**Loc ID 333566 Inspector Name: Kosola, Jason On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 53255Name of Operator: MARALEX RESOURCES INCAddress: P O BOX 338City: IGNACIO State: CO Zip: 81137**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
- 
- ☒
- FOLLOW UP INSPECTION REQUIRED
- 
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**4 Number of Comments2 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	
Bechtolt, Phoebe		pbechtolt@maralexinc.com	
, O'hare		mollieo@maralexinc.com	<a href="#">San Juan inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214932	WELL	PA	01/03/2022	GW	067-06537	SHELHAMMER 1	EI
465913	SPILL OR RELEASE	AC	07/29/2019		-	Shelhammer Compressor	EI

**General Comment:**

This is an environmental inspection to document status of Remediation 21214. Partially buried vessel excavation appears to have impacts from a release from the tank. See corrective action.

Location				
Overall Good: <input type="checkbox"/>				
Emergency Contact Number:				
Comment:				Date: _____
Corrective Action:				
Good Housekeeping:				
Type	TRASH			
Comment:	Trash in soil pile and other trash on location. See attached photos			
Corrective Action:	Comply with Rule 606			Date: 11/21/2024
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
Comment:	Evidence of possible release from partially buried vessel. See attached photos.			
Corrective Action:	Conduct spill investigation and conduct soil sampling around tank as part of Remediation 21214. Submit soil sample results on Form 27 Supplemental.			Date: 12/31/2024
In Containment: No				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				
Venting:				
Yes/No				
Comment:				
Corrective Action:				Date: _____
Flaring:				
Type				
Comment:				
Corrective Action:				Date: _____

Inspected Facilities				
Facility ID: 214932	Type: WELL	API Number: 067-06537	Status: PA	Insp. Status: EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 465913	Type: SPILL OR	API Number: -	Status: AC	Insp. Status: EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708700064	Environmental inspection photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6786581">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6786581</a>