

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403988245

Date Received:
11/14/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 3 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10694
Name of Operator: PROVIDENCE OPERATING LLC DBA POCO OPERATING
Address: 16400 DALLAS PARKWAY SUITE 400
City: DALLAS State: TX Zip: 75428

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Grimes, Meghan		mgrimes@providence-energy.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 708201701
Inspection Date: 10/16/2024 FIR Submit Date: 10/24/2024 FIR Status:

Inspected Operator Information:

Company Name: PROVIDENCE OPERATING LLC DBA POCO OPERATING Company Number: 10694
Address: 16400 DALLAS PARKWAY SUITE 400
City: DALLAS State: TX Zip: 75428

LOCATION - Location ID: 460271

Location Name: Double J Number: 35-11 Pad County:
Qtrqr: NWSE Sec: 35 Twp: 1N Range: 65W Meridian: 6
Latitude: 40.006990 Longitude: -104.629770

FACILITY - API Number: 05-123-00 Facility ID: 460271

Facility Name: Double J Number: 35-11 Pad
Qtrqr: NWSE Sec: 35 Twp: 1N Range: 65W Meridian: 6
Latitude: 40.006990 Longitude: -104.629770

CORRECTIVE ACTIONS:

3 CA# 200032

Corrective Action: At the time of this inspection, ECMC Staff notified on-site Pumper to inform of the motor/pump skid fluid and secondary containment (day tank) debris that appeared to have been mixed with day tank contents.

Date: 10/26/2024

Comply with Rule 1002.f.(2)B. Implement or modify BMPs for improved material handling and spill prevention. Operator shall report contents from the pump/motor skid and from the secondary containment and include detail within the FIRR.

Response: CA COMPLETED Date of Completion: 10/26/2024

A Workover rig was on location at the time of inspection. The rig has since moved off location. The issue was

Operator Comment: coming from the pump skid that needed its packing changed and it was leaking production water and the problem was corrected same day it was found the pics above are the area where the pump skid was and where the rig itself was

ECMC Decision: _____

ECMC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: _____

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Andrea Gross

Signed: _____

Title: Permit Agent

Date: 11/14/2024 2:40:12 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403988245	FIR RESOLUTION SUBMITTED
403995423	photos
403995429	Photos
403995432	Photos

Total Attach: 4 Files