

# Inspection Photos

November 12th, 2024

Operator: Simcoe LLC - 10749

Location ID: 307009

Inspection Document #: 714001476

La Plata County, CO

Township: NWNW 5 34N 7W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Gearhart 01-05 2  
Location ID: 307009

11/12/24  
42° NE



Photo 1. View of well disturbance taken from the access point facing center.

GEARHART 01-05 2  
SIMCOE LLC  
ELEVATION: 7397 API #: 067-09503 DWR #: 70746-F  
NAME OF TRIBE: N/A LEASE TYPE: FEE  
LEASE #: N/A CA #: COCS098  
SURFACE LOCATION: NWW SEC 5 - T34N - R7W 1195 FNL 1161 FWL  
BOTTOM HOLE LOCATION: SAME AS SURFACE LOCATION  
LATITUDE: 37.24807713 LONGITUDE: -107.6652033  
NEAREST ADDRESS: 38054 E HWY 100  
CONTROL CENTER 24 HR. PHONE #: 970-247-6916  
EMERGENCY CONTACT #: 911

Inspection Photos  
Location Name: Gearhart 01-05 2  
Location ID: 307009

11/12/24  
75° E



**Photo 2.** Southern reclamation area composed of Sand Dropseed, Smooth Brome and Western Wheatgrass. No erosion observed in the southern portion of the location.

Inspection Photos  
Location Name: Gearhart 01-05 2  
Location ID: 307009



**Photo 3.** Impacted surface material observed at well head.

Inspection Photos  
Location Name: Gearhart 01-05 2  
Location ID: 307009



**Photo 4.** Erosion forming at the access point, future maintenance for additional stabilization at access point is advised.

Inspection Photos  
Location Name: Gearhart 01-05 2  
Location ID: 307009



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 5.** Reference area composed of Western Wheatgrass, Gambel Oak and Juniper.

API #: 067-09503