

Inspection Photos

Location Name: TEP Rocky Mountain LLC LANGSTAFF RMV 12-16 Pad

Location # 335188



Nov 14, 2024 at 1:09:18 PM
CO

Photo # 88 From entrance to location



Nov 14, 2024 at 1:09:32 PM
CO

Photo # 89 From entrance to location

Inspection Photos

Location Name: TEP Rocky Mountain LLC LANGSTAFF RMV 12-16 Pad

Location # 335188




Photo # 90 Location



Photo # 91 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC LANGSTAFF RMV 12-16 Pad

Location # 335188



Photo # 92 Location



Photo # 93 Location



Inspection Photos

Location Name: TEP Rocky Mountain LLC LANGSTAFF RMV 12-16 Pad

Location # 335188



Photo # 94 Location



Photo # 95 Mechanical Condition - Possible leak on the Langstaff RWF 724-16 wellhead

Inspection Photos

Location Name: TEP Rocky Mountain LLC LANGSTAFF RMV 12-16 Pad

Location # 335188



Photo # 96 Mechanical Condition - Possible leak on the Langstaff RWF 724-16 wellhead



Photo # 97 Mechanical Condition - Possible leak on the Langstaff RWF 724-16 wellhead