

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/14/2024

Submitted Date:

11/14/2024

Document Number:

708905036**FIELD INSPECTION FORM**Loc ID 335188 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: 1058 COUNTY ROAD 215City: PARACHUTE State: CO Zip: 81635**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**23 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	
, Engineering		dnr_cogccengineering@state.co.us	
Haverkamp, Curtis		curtis.haverkamp@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
281746	WELL	PR	12/02/2005	GW	045-11522	LANGSTAFF RWF 323-16	PR
281747	WELL	PR	08/06/2006	GW	045-11523	LANGSTAFF RWF 423-16	PR
281748	WELL	PR	12/02/2005	GW	045-11524	LANGSTAFF RWF 413-16	PR
281749	WELL	PR	09/11/2006	GW	045-11525	LANGSTAFF RWF 513-16	PR
434347	WELL	PR	08/01/2024	GW	045-22157	Langstaff RWF 724-16	PR

**General Comment:****CECMC Inspection Report Summary**

On 11/14/2024 at approximately 13:09 hours, I, Compliance Specialist, Wayne Smelser Conducted an on-site inspection at TEP ROCKY MOUNTAIN LLC LANGSTAFF RMV12-16 Pad. Location # 335188 in Garfield County Colorado. Location is within High Priority/Density Habitat areas & in close proximity to NSO Habitat area. Location is approximately 229 yards from a creek/drainage that contributes to the Colorado River. While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Equipment - Mechanical Condition - Possible leak on the Langstaff RWF 724-16 wellhead with a CA date of 11/15/2024

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This is a summary of inspection report.

Split pad/Remote location - Shared facilities with the LANGSTAFF RWF 324-16 pad, location # 335192.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: [911/970-285-9377](tel:9119702859377)

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No \_\_\_\_\_

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	SEPARATOR		
Comment:	<a href="#">Hog panels</a>		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	<a href="#">Hog panels</a>		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	<a href="#">Hog panels</a>		
Corrective Action:		Date:	

<b>Equipment:</b>				corrective date
Type: Deadman # & Marked	# 1			
Comment:	Marked			
Corrective Action:				Date:
Type: Gas Meter Run	# 9			
Comment:				
Corrective Action:				Date:
Type: Bradenhead	# 5			
Comment:	Taylor plugs located on all bradenhead, bradenhead valves are accessible.			
Corrective Action:				Date:
Type: Bird Protectors	# 5			
Comment:				
Corrective Action:				Date:
Type: Plunger Lift	# 5			
Comment:	All wells on plunger lift			
Corrective Action:				Date:
Type: Horizontal Heated Separator	# 9			
Comment:				
Corrective Action:				Date:
Type: Other	# 1			
Comment:	<p>Mechanical Condition - Possible leak on the Langstaff RWF 724-16 wellhead/gas bubbling up near wellhead through water in cellar.</p> <p>At approximately 13:13 hours observed possible leak on the RWF 724-16 wellhead. Observed gas bubbling up near wellhead through water in cellar. At approximately 13:16 hours I called &amp; notified Mike Gardner with TEP of the possible leak &amp; that I was issuing a 24 hour corrective action on the observed compliance issue. He said he'd notify the supervisor for that area &amp; get him to check it out. Mike texted me at 15:11 hours &amp; notified me TEP personnel had looked at the wellhead &amp; believe the stem packing on one of the master valves is causing the leak. A crew will be on location tomorrow morning to make repairs.</p>			
Corrective Action:	All Production Facilities, valves, pipes, fittings, and vessels will be securely fastened or sealed, inspected at regular intervals, and maintained in good mechanical condition.			Date: 11/15/2024

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		,
Comment:	Tank equipped with telemetry				
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Inspector Name: Smelser, Wayne

Metal	Adequate	Walls Sufficent			
Comment:	Centralized containment				
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLs	STEEL AST		,
Comment:	Tanks equipped with telemetry				
Corrective Action:					Date:
Paint					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent			
Comment:	Centralized containment				
Corrective Action:					Date:
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities									
Facility ID:	281746	Type:	WELL	API Number:	045-11522	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	281747	Type:	WELL	API Number:	045-11523	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	281748	Type:	WELL	API Number:	045-11524	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	281749	Type:	WELL	API Number:	045-11525	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	434347	Type:	WELL	API Number:	045-22157	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						Sparse
Retention Ponds						
Berms						
Ditches						
		Ditches				
Rip Rap						
Sediment Traps						
		Compaction				Small amount of light compaction
		Culverts				
		Gravel				Sparse to none in sections
Compaction						

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**ECMC Comments**

Comment	User	Date
Please refer to Equipment for corrective action.	smelserw	11/14/2024
Split pad/Remote location - Shared facilities with the LANGSTAFF RWF 324-16 pad, location # 335192.		

**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708905037	Inspection 708905036 video 1 (RWF 724-16)	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6787649">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6787649</a>
708905038	Inspection 708905036 video 2 (RWF 724-16)	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6787650">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6787650</a>
708905039	Inspection 708905036 Stormwater photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6787651">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6787651</a>
708905040	Inspection 708905036 photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6787652">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6787652</a>