

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/28/2024

Submitted Date:

11/07/2024

Document Number:

715201145**FIELD INSPECTION FORM**Loc ID 321082 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 76175Name of Operator: SANDLIN OIL CORPAddress: PO BOX 430City: DACONO State: CO Zip: 80514-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:14 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Sandlin, Gary		SandlinOilCorporation@gmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
205982	WELL	SI	12/01/2022	GW	009-06397	LEACH 1	SI

General Comment:

SE Compliance Specialist Brian Welsh conducted a routine field inspection of the well location and equipment

Form 6N (403413236) has been Approved

Form 6A (403383668) has been Approved with a plug date of 12/31/27

Location**Lease Road:**

Type	Access		
comment:	Trail through farm ground		
Corrective ActionL		Date:	

Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:	Lease sign by separator		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Sticker is faded and needs replaced		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	11/28/2024

Emergency Contact Number:

Comment:			
Corrective Action:		Date:	

Good Housekeeping:

Type	WEEDS		
Comment:	Dead weeds across location		
Corrective Action:	Comply with Rule 606	Date:	11/28/2024

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

			corrective date
Type: Ancillary equipment	# 1		
Comment:	Telemetry equipment at meter shed		
Corrective Action:		Date:	
Type: Gas Meter Run	# 0		
Comment:	Central meter sheds have been removed		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	NSCO model 40		
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:	Vertical gas separator on east side of water tank		
Corrective Action:		Date:	

Type: Prime Mover	# 1	
Comment:	Arrow gas engine	
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	Open Top		37.179880,-102.133510
Comment:	Fiberglass open top water tank				
Corrective Action:	Netting needs repaired				Date: 11/28/2024

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate
Comment:	Berms are inadequate and need maintenance			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 603.o.			Date: 11/28/2024

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	205982	Type:	WELL	API Number:	009-06397	Status:	SI	Insp. Status:	SI
Producing Well									
Comment:	Well is SI at time of inspection. Meter shed has been removed and is not capable of production. Form 6A (403383668) has been Approved with a plug date of 12/31/27								
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass	Other	Pass			

Comment: Location and access are farmed over

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403988014	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6779317
715201175	location photo	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6779308