

Operator: HPR

Location Name: RSU Anschutz Fed 4-62-2_1 SWNW

Loc ID: 436165

Inspection: 713901038









CA: Stained soil observed by diesel tanks on the West side of the pad. Remove stained soil per Rule 912.a.

CA Resolution: Operator removed identified stained soil to comply with the 900 series.

CA: Along the access road and at the entrance cattle guard at the well location the roadside ditch and riprap check dams were full of sediment. Sediment should be removed from access road ditches for BMP's to continue to work properly. Remove sediment accrued in stormwater ditches and riprap per Rule 1002.f.

CA Resolution: Operator has reported riprap and stormwater ditches have been appropriately cleared of sediment to comply with the 1000 series.