

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/12/2024

Submitted Date:

11/12/2024

Document Number:

708303056

**FIELD INSPECTION FORM**

Loc ID 311638	Inspector Name: Morris, Matthew	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input checked="" type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED  <b>Findings:</b> 8 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested																																																																																																																							
<b>Operator Information:</b> ECMC Operator Number: 10456 Name of Operator: CAERUS PICEANCE LLC Address: 1001 17TH STREET #1600 City: DENVER State: CO Zip: 80202																																																																																																																											
<b>Contact Information:</b> <table border="1" style="width:100%; border-collapse: collapse;"> <tr> <th>Contact Name</th> <th>Phone</th> <th>Email</th> <th>Comment</th> </tr> <tr> <td>, CAERUS</td> <td></td> <td>ecmc.inspections@qb-energy.com</td> <td></td> </tr> </table>				Contact Name	Phone	Email	Comment	, CAERUS		ecmc.inspections@qb-energy.com		<b>ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE</b>																																																																																																															
Contact Name	Phone	Email	Comment																																																																																																																								
, CAERUS		ecmc.inspections@qb-energy.com																																																																																																																									
<b>Inspected Facilities:</b> <table border="1" style="width:100%; border-collapse: collapse;"> <thead> <tr> <th>Facility ID</th> <th>Type</th> <th>Status</th> <th>Status Date</th> <th>Well Class</th> <th>API Num</th> <th>Facility Name</th> <th>Insp Status</th> </tr> </thead> <tbody> <tr><td>282774</td><td>WELL</td><td>PR</td><td>12/01/2009</td><td>GW</td><td>045-11838</td><td>N. PARACHUTE MF07C-4 CO4 696</td><td>PR</td></tr> <tr><td>282776</td><td>WELL</td><td>PR</td><td>04/27/2007</td><td>GW</td><td>045-11836</td><td>N.PARACHUTE MF 13D CO4 696</td><td>PR</td></tr> <tr><td>282777</td><td>WELL</td><td>PR</td><td>04/12/2007</td><td>GW</td><td>045-11835</td><td>N. PARACHUTE MF04D CO4 696</td><td>PR</td></tr> <tr><td>282778</td><td>WELL</td><td>PR</td><td>01/23/2006</td><td>GW</td><td>045-11834</td><td>N.PARACHUTE MF02C CO4 696</td><td>PR</td></tr> <tr><td>282779</td><td>WELL</td><td>PR</td><td>01/23/2006</td><td>GW</td><td>045-11833</td><td>N.PARACHUTE MF08C CO4 696</td><td>PR</td></tr> <tr><td>282780</td><td>WELL</td><td>PR</td><td>01/23/2006</td><td>GW</td><td>045-11832</td><td>N.PARACHUTE MF03A CO4 696</td><td>PR</td></tr> <tr><td>282781</td><td>WELL</td><td>PR</td><td>11/30/2009</td><td>GW</td><td>045-11831</td><td>N. PARACHUTE MF06C-4 CO4 696</td><td>PR</td></tr> <tr><td>282784</td><td>WELL</td><td>PR</td><td>01/23/2006</td><td>GW</td><td>045-11829</td><td>N.PARACHUTE MF08A CO4 696</td><td>PR</td></tr> <tr><td>282785</td><td>WELL</td><td>PR</td><td>01/23/2006</td><td>GW</td><td>045-11828</td><td>N.PARACHUTE MF01C CO4 696</td><td>PR</td></tr> <tr><td>282786</td><td>WELL</td><td>PR</td><td>07/24/2009</td><td>GW</td><td>045-11827</td><td>N. PARACHUTE MF07A-4 CO4 696</td><td>PR</td></tr> <tr><td>284640</td><td>WELL</td><td>PR</td><td>12/01/2009</td><td>GW</td><td>045-12249</td><td>N. PARACHUTE MF06B-4 CO4 696</td><td>PR</td></tr> <tr><td>295477</td><td>WELL</td><td>PR</td><td>03/01/2010</td><td>GW</td><td>045-15766</td><td>N. PARACHUTE MF01C-4 CO4 696</td><td>PR</td></tr> <tr><td>295478</td><td>WELL</td><td>PR</td><td>07/14/2011</td><td>GW</td><td>045-15767</td><td>N. PARACHUTE MF13D-31 CO4 69</td><td>PR</td></tr> <tr><td>295479</td><td>WELL</td><td>PR</td><td>02/20/2010</td><td>GW</td><td>045-15768</td><td>N. PARACHUTE MF04B-3 CO4 696</td><td>PR</td></tr> </tbody> </table>				Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	282774	WELL	PR	12/01/2009	GW	045-11838	N. PARACHUTE MF07C-4 CO4 696	PR	282776	WELL	PR	04/27/2007	GW	045-11836	N.PARACHUTE MF 13D CO4 696	PR	282777	WELL	PR	04/12/2007	GW	045-11835	N. PARACHUTE MF04D CO4 696	PR	282778	WELL	PR	01/23/2006	GW	045-11834	N.PARACHUTE MF02C CO4 696	PR	282779	WELL	PR	01/23/2006	GW	045-11833	N.PARACHUTE MF08C CO4 696	PR	282780	WELL	PR	01/23/2006	GW	045-11832	N.PARACHUTE MF03A CO4 696	PR	282781	WELL	PR	11/30/2009	GW	045-11831	N. PARACHUTE MF06C-4 CO4 696	PR	282784	WELL	PR	01/23/2006	GW	045-11829	N.PARACHUTE MF08A CO4 696	PR	282785	WELL	PR	01/23/2006	GW	045-11828	N.PARACHUTE MF01C CO4 696	PR	282786	WELL	PR	07/24/2009	GW	045-11827	N. PARACHUTE MF07A-4 CO4 696	PR	284640	WELL	PR	12/01/2009	GW	045-12249	N. PARACHUTE MF06B-4 CO4 696	PR	295477	WELL	PR	03/01/2010	GW	045-15766	N. PARACHUTE MF01C-4 CO4 696	PR	295478	WELL	PR	07/14/2011	GW	045-15767	N. PARACHUTE MF13D-31 CO4 69	PR	295479	WELL	PR	02/20/2010	GW	045-15768	N. PARACHUTE MF04B-3 CO4 696	PR
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status																																																																																																																				
282774	WELL	PR	12/01/2009	GW	045-11838	N. PARACHUTE MF07C-4 CO4 696	PR																																																																																																																				
282776	WELL	PR	04/27/2007	GW	045-11836	N.PARACHUTE MF 13D CO4 696	PR																																																																																																																				
282777	WELL	PR	04/12/2007	GW	045-11835	N. PARACHUTE MF04D CO4 696	PR																																																																																																																				
282778	WELL	PR	01/23/2006	GW	045-11834	N.PARACHUTE MF02C CO4 696	PR																																																																																																																				
282779	WELL	PR	01/23/2006	GW	045-11833	N.PARACHUTE MF08C CO4 696	PR																																																																																																																				
282780	WELL	PR	01/23/2006	GW	045-11832	N.PARACHUTE MF03A CO4 696	PR																																																																																																																				
282781	WELL	PR	11/30/2009	GW	045-11831	N. PARACHUTE MF06C-4 CO4 696	PR																																																																																																																				
282784	WELL	PR	01/23/2006	GW	045-11829	N.PARACHUTE MF08A CO4 696	PR																																																																																																																				
282785	WELL	PR	01/23/2006	GW	045-11828	N.PARACHUTE MF01C CO4 696	PR																																																																																																																				
282786	WELL	PR	07/24/2009	GW	045-11827	N. PARACHUTE MF07A-4 CO4 696	PR																																																																																																																				
284640	WELL	PR	12/01/2009	GW	045-12249	N. PARACHUTE MF06B-4 CO4 696	PR																																																																																																																				
295477	WELL	PR	03/01/2010	GW	045-15766	N. PARACHUTE MF01C-4 CO4 696	PR																																																																																																																				
295478	WELL	PR	07/14/2011	GW	045-15767	N. PARACHUTE MF13D-31 CO4 69	PR																																																																																																																				
295479	WELL	PR	02/20/2010	GW	045-15768	N. PARACHUTE MF04B-3 CO4 696	PR																																																																																																																				

295480	WELL	PR	02/15/2010	GW	045-15769	N. PARACHUTE MF03C-4 C04 696	PR
295481	WELL	PR	01/14/2010	GW	045-15770	N. PARACHUTE MF02C-4 CO4 696	PR
295482	WELL	PR	02/10/2010	GW	045-15771	N. PARACHUTE MF06A-4 CO4 696	PR
295483	WELL	PR	02/22/2010	GW	045-15772	N. PARACHUTE MF02B-4 CO4 696	PR
295487	WELL	PR	01/13/2010	GW	045-15777	N. PARACHUTE MF13C-31 C04 69	PR

**General Comment:**

[CECMC Inspection Report Summary](#)

On 11/12/2024 at approximately 10:35, Compliance Inspector Matthew Morris conducted a follow-up inspection at CAERUS PICEANCE LLC, N.PARACHUTE-66S96W/4NENW at Location ID #311638 in Garfield County, Colorado.

During the inspection, the following compliance issues were observed:

1) Stormwater; refer to Stormwater section

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

**Location**Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/(970)285-2615

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Concrete barriers		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Gas meters, lift, heaters, and chemical tanks protected by concrete barriers.		
Corrective Action:		Date:	

**Equipment:**

Type: Gas Meter Run	# 19		corrective date
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 19		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 19		

Comment: <a href="#">Gas lift</a>		Date:
Corrective Action:		Date:
Type: Ancillary equipment	# 3	
Comment: <a href="#">CataDyne heaters</a>		Date:
Corrective Action:		Date:
Type: Plunger Lift	# 19	
Comment:		Date:
Corrective Action:		Date:
Type: Ancillary equipment	# 3	
Comment: <a href="#">Chemical tanks</a>		Date:
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	OTHER	STEEL AST		,
Comment:					
Corrective Action:		Date:			

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	120 bbls
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:		Date:		

**Venting:**

Yes/No	NO	
Comment:		Date:
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities				
Facility ID:	282774	Type:	WELL	API Number: 045-11838 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:				
Corrective Action:				Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	282776	Type:	WELL	API Number: 045-11836 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:				
Corrective Action:				Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	282777	Type:	WELL	API Number: 045-11835 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:				
Corrective Action:				Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	282778	Type:	WELL	API Number: 045-11834 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:				
Corrective Action:				Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	282779	Type:	WELL	API Number: 045-11833 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:				
Corrective Action:				Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	282780	Type:	WELL	API Number: 045-11832 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:				
Corrective Action:				Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	282781	Type:	WELL	API Number: 045-11831 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:				
Corrective Action:				Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	282784	Type:	WELL	API Number: 045-11829 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:				
Corrective Action:				Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				

<u>Producing Well</u>				
Comment:				
Corrective Action:				Date: <input type="text"/>
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	282785	Type:	WELL	API Number: 045-11828 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:				
Corrective Action:				Date: <input type="text"/>
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	282786	Type:	WELL	API Number: 045-11827 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:				
Corrective Action:				Date: <input type="text"/>
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	284640	Type:	WELL	API Number: 045-12249 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:				
Corrective Action:				Date: <input type="text"/>
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	295477	Type:	WELL	API Number: 045-15766 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:				
Corrective Action:				Date: <input type="text"/>
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	295478	Type:	WELL	API Number: 045-15767 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:				
Corrective Action:				Date: <input type="text"/>
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	295479	Type:	WELL	API Number: 045-15768 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:				
Corrective Action:				Date: <input type="text"/>
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	295480	Type:	WELL	API Number: 045-15769 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:				

Corrective Action:		Date:	
--------------------	--	-------	--

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	295481	Type:	WELL	API Number:	045-15770	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

<b>Producing Well</b>							
Comment:							
Corrective Action:				Date:			

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	295482	Type:	WELL	API Number:	045-15771	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

<b>Producing Well</b>							
Comment:							
Corrective Action:				Date:			

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	295483	Type:	WELL	API Number:	045-15772	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

<b>Producing Well</b>							
Comment:							
Corrective Action:				Date:			

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	295487	Type:	WELL	API Number:	045-15777	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

<b>Producing Well</b>							
Comment:							
Corrective Action:				Date:			

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				
				Material Handling And Spill Prevention		
		Compaction				
Compaction						
		Tracking Pad				
Berms						
		Ditches				
Gravel						

Comment: Refer to FIR #707800703. Cut slope is lacking stabilization and actively eroding at time of inspection. Vegetation at top of cut slope is being undermined and roots are exposed. Places with sparse to no gravel & light compaction are present on lease road. Sparse to no gravel and light compaction could lead to future stabilization and tracking issues.

Corrective Action: Install, maintain or repair required BMPs.

Date: 03/21/2024

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403992281	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6784019">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6784019</a>
708303057	Photo Log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6784017">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6784017</a>